



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

IMPORTANT SAFETY RECALL INFORMATION



Issued in Accordance
With Federal Law



SAFETY RECALL



\*\*\*\*\*SNGLP



000001
T1 P1

25PACH

Recall Notice: 25PACH - 20k Steerable Pusher Insufficient
Air Volume Non-Compliance with FMVSS 121

SAFETY RECALL

12/31/25

Subject: 25PACH: 20k Steerable Pusher Insufficient Air Volume Non-Compliance with FMVSS 121

NHTSA: 25V795

Expiration Date: None

Peterbilt Motors Company  
Customer Service Department  
C/O PACCAR Parts  
750 Houser Way North  
Renton, WA 98057  
(425) 828-5888

## IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s) with VIN(s) listed at the bottom or back of this page.

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that certain model year 2026 Model 567 and 589 chassis manufactured between 02/11/2025 and 09/10/2025, fail to conform to Federal Motor Vehicle Safety Standard No. 121, "Air Brake Systems."



<b>What is the problem?</b>	Certain tractors with 20k steerable pusher axles have insufficient air volume to meet FMVSS 121 requirements. Insufficient air volume may reduce service brake performance, which may increase the risk of a crash.
<b>What will your dealer do?</b>	Dealers will add and/or replace air tanks to correct the insufficient air volume, free of charge.
<b>What should you do?</b>	Contact your dealer immediately to schedule a repair. This repair may require up to 5 hours of labor.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at [www.Peterbilt.com](http://www.Peterbilt.com). When scheduling this repair, please refer to recall 25PACH: 20k Steerable Pusher Insufficient Air Volume Non-Compliance with FMVSS 121 and the VIN(s) listed in this letter. You may be eligible for reimbursement if you performed this repair before receiving notification of the recall. For more information, please e-mail [servicebulletins@PACCAR.com](mailto:servicebulletins@PACCAR.com). Your dealer will coordinate pre-ordering of parts for your vehicle to minimize downtime.

If you believe this remedy was not available to you within a reasonable amount of time and free of charge, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590; call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or visit <http://www.safercar.gov>.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to [servicebulletins@paccar.com](mailto:servicebulletins@paccar.com).

We appreciate your attention to this matter and value your loyalty to Peterbilt and its dealer network.

Sincerely,  
Peterbilt Customer Service

Our records indicate that these vehicles are affected by 25PACH and are owned by [REDACTED]

[REDACTED]  
[REDACTED]