


## RECALL 25V005 / 2025-008 REMEDY INSTRUCTIONS

	Make(s): SHASTA OASIS & SPIRIT Model(s): MANY, SEE BELOW Model Year(s): 2025	Repair Code: RC-030-01-00-004677 Allotted Time: .50 HRS. Inspection Code: RC-030-05-00-004676 Allotted Time: 17 HRS
	Concern: According to the recall 24E105 filed by InVision: "The center internal aluminum burner tube connecting the gas valve to the cook top burners can be fractured."	Photo(s) Required: N/A Prior Authorization Required: YES Part(s) Kit Number: F100697534 Part(s) Return: NO, FIELD DESTROY

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

CERTAIN 2025 – SHASTA OASIS: SST31QB, SST525BHS, SST526BH, SST526DB, SST526RBS, SST530QB & SST532BEDS  
 CERTAIN 2025 – SPIRIT: SBT5260BH, SBT5250BHS, SBT5210CK, SBT5320BEDS, SBT5260RBS & SBT310QB


**PLEASE SEE ATTACHED INSPECTION AND REMEDY INSTRUCTIONS**

## GAS COOKTOP

**GAS LINE INSPECTION AND REPLACEMENT  
FOR FRONT BURNER**




**MODELS:  
Three Burner  
410-2030**



1. Lift glass-lid



2. Lift grate and set to the side




## GAS COOKTOP

**GAS LINE INSPECTION AND REPLACEMENT  
FOR FRONT BURNER**




**MODELS:  
Three Burner  
410-2030**



**3. Remove 2 screws from rear of pan**



**4. Lift pan/glass-top away  
from base and set to the side.**





## GAS COOKTOP

### GAS LINE INSPECTION AND REPLACEMENT FOR FRONT BURNER



**MODELS:**  
Three Burner  
410-2030



5. Fill a cup with water and squeeze in a dime-sized amount of dish soap. Then, stir the soap and water together until it starts to form suds.


6. With a small brush, apply the soapy water to the areas indicated in the image to the left.

7. Make sure the cooktop is connected to a gas supply and the valves are opened.

Next turn the Front Burner Knob to the "Hi" position (flame sense technology will only allow gas to flow 30-45 sec before gas flow is automatically shut off.)

8. Visually inspect the areas for any bubbles forming which indicates a leak.

9. If no leaks are detected, record the serial number and re-assemble the unit; If a leak is detected move on to the next steps to replace the faulty gas line with a new one.





## GAS COOKTOP

### GAS LINE INSPECTION AND REPLACEMENT FOR FRONT BURNER



**MODELS:**  
Three Burner  
410-2030



10. Brace burner with one hand so its position isn't altered .

11. With a 14mm wrench carefully turn the connector counter-clockwise.

12. With a 16mm wrench carefully turn the connector counter-clockwise.

13. Follow the procedure in reverse to install new gas line and reassemble cooktop.

