


RECALL 25V229 / 2025-188 REMEDY INSTRUCTIONS

 FOREST RIVER	Make(s): BROOKSTONE Model(s): BKF398MBL Model Year(s): 2025	Repair Code: RC-632-09-00-004702 Allotted Time: 2.00 HRS. Inspection Code: RC-632-05-00-004704 Allotted Time: .10 HRS
	Concern: The waste water holding tank(s) ventilation pipe may not be terminated exterior of the vehicle.	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: F100732260 Part(s) Return: NO

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

STEP 1: REMOVE OVERHEAD CABINET;

- OVERHEAD LOCATED RIGHT BY THE ENTRY DOOR. JUST ON THE OTHER SIDE OF THE COAT CLOSET

STEP 2: PULL WALL PANEL THAT IS LOCATED BEHIND THE OVERHEAD CABINET THAT WAS REMOVED;

STEP 3: INSTALL NEW SECTION OF PIPE TO THE EXISTING PIPE THAT IS BEHIND THE WALL PANEL;

- EXTEND THROUGH THE ROOF ABOUT 2";
 - USE A 1/2" DRILL BIT TO DRILL THROUGH CLEAT AND ROOF TO MAKE A PILOT HOLE

STEP 4: USE HOLE SAW SMALLER THAN THE VENT PIPE BASE AND USE THE 1/2" HOLE AS YOUR CENTER GUIDE AND CUT THE HOLE THROUGH THE ROOF;

STEP 5: INSTALL VENT PIPE THROUGH ROOF AND GLUE TO CONNECTION AT THE BOTTOM;

STEP 5: REINSTALL WALL PANEL;

STEP 6: REINSTALL OVERHEAD CABINET;

STEP 7: PLACE PROVIDED ROOF VENT CAP BASE AND TOP OVER VENT PIPE;

STEP 8: TEST FOR PROPER FUNCTIONALITY;

STEP 9: CLAIM REPAIR CODE;