


# RECALL 25V287 / 2025-235 REMEDY INSTRUCTIONS

 <b>FOREST RIVER</b>	Make(s): CAMPSITE RESERVE Model(s): MANY, SEE BELOW Model Year(s): 2025	Repair Code: RC-003-09-00-004715 Allotted Time: .30 HRS. Inspection Code: RC-003-05-00-004714 Allotted Time: .10 HRS.
	Concern: The solar controller may be wired to constant hot of a 30AMP mini-breaker, whereas it should be on the breaker side.	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: N/A Part(s) Return: N/A

**Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.**

CERTAIN 2025 – CAMPSITE RESERVE - CRT19KB, CRT26BW, CRT26CJL & CRT26TH

## **INSPECTION:**

STEP 1: LOCATE THE SOLAR CONTROLLER WIRE ON THE 30AMP MINI-BREAKER BEHIND THE CHASSIS BULKHEAD;

- IF THE SOLAR CONTROLLER WIRE IS HOOKED TO THE SIDE AS THE RED/WHITE WIRE/BREAKER SIDE OF THE MINI-BREAKER, CLAIM INSPECTION ONLY;
- IF THE SOLAR CONTROLLER WIRE IS HOOKED TO THE SAME SIDE AS THE BLACK BATTERY POSITIVE, PROCEED TO REMEDY;

## **REMEDY:**

STEP 1: LOCATE THE RED/WHITE POSITIVE WIRE FROM THE SOLAR CONTROLLER;

STEP 2: USING A 3/8" SOCKET, REMOVE THE NUT ON THE MINI-BREAKER (BOTH POSTS);

STEP 3: REMOVE THE SOLAR CONTROLLER WIRE FROM THE POST WITH THE BLACK WIRE;

STEP 4: INSTALL THE SOLAR CONTROLLER WIRE ONTO THE POST WITH THE OTHER RED/WHITE WIRE;

STEP 5: REINSTALL THE TWO – 3/8" NUTS AND TIGHTEN DOWN, ENSURING THERE IS NO PLAY IN THE WIRES;

STEP 6: TEST FOR PROPER FUNCTIONALITY;

STEP 7: CLAIM REPAIR CODE.

PHOTO FOR REFERENCE (INCORRECTLY WIRED):

