


## RECALL 25V307 REMEDY INSTRUCTIONS

 <b>FOREST RIVER</b>	Make(s): Cherokee Model(s): ACKT271RK Model Year(s): 2025	Repair Code: RC-047-03-00-004717 Allotted Time: 1.00 HRS. Inspection Code: RC-047-05-00-004716 Allotted Time: .10 HRS.
	Concern: The vehicle may be missing the egress window(s).	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: SEE BELOW Part(s) Return: NO/FIELD DESTROY

**Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.**

### **PART NUMBERS OF THE REMEDY KIT:**

F100625820 – WINDOW - EXIT

F100033230 - TRIM RING

### **REMEDY:**

STEP 1: REMOVE THE NON-EGRESS WINDOW FROM THE DOOR SIDE FRONT WALL (48" X 36" WINDOW) AND DISCARD;

STEP 2: INSTALL THE EGRESS WINDOW (48" X 36") IN THE DOOR SIDE FRONT WALL OPENING;

- APPLY SEALANT AS NEEDED TO WINDOW FRAME;
- USE THIS WINDOWS SPECIFIC TRIM RING AND SCREWS TO REINSTALL
- APPLY CAP SEAL AS NEEDED

STEP 3: ENSURE TO LOCATE THE "EXIT" STICKER TO THE REAR WALL NEXT TO/AT THE IMMEDIATE TOP OR BOTTOM TO THE WINDOW SO IT IS VISABLE WITHOUT MOVING ITEMS;

STEP 4: TEST FOR PROPER FUNCTIONALITY;

STEP 5: CLAIM REPAIR CODE.