

Parts Bulletin

TITLE:

Recall RP1061 - PS2 BCM2 Software, Certain Model Year 2021-2025 Polestar 2

GROUP:

52

NO:

RP1061

CAR MARKET:

United States and Canada

REVISIONS:

ISSUE DATE:

2025-06-17

STATUS DATE:

2025-06-17**Page 1 of 1**

Polestar Automotive USA, on behalf of Polestar Performance AB, have decided to launch Recall RP1061 on certain model year 2021 to 2025 Polestar 2 vehicles.

Polestar has identified that a loss of brake functionality may occur while in “One Pedal Drive” mode after an extended coast down period. Affected customers may experience a loss of braking.

As a result, loss of brake functionality will increase the risk of a crash.

To remedy the affected vehicles, Polestar will release a software update. This software is currently available in VIDA and will be made available via over-the-air (OTA) later this week. If the vehicle has **P3.6.4 or later** then this recall has been satisfied.

A total of 2 U.S. and 113 Canadian vehicles are affected by this recall.

The following part numbers apply:

Part Number	Qty	Failing Part	Description
32292674	1	F	Total Upgrade