

Parts Bulletin

TITLE:

Recall RP1060**Model Year: 2025 Polestar 3 vehicles**

GROUP:

83

NO:

RP1060

CAR MARKET:

United States

REVISIONS:

ISSUE DATE:

2025-06-27

STATUS DATE:

2025-06-27**Page 1 of 1**

Polestar Automotive USA, on behalf of Polestar Performance AB, have decided to launch Recall RP1060 on certain model year 2025 Polestar 3 vehicles.

Polestar has identified that the panoramic glass roof may not be mounted to the body according to specification. There may be residual masking tape present from the factory repaint station.

As a result, the panoramic glass roof may separate from the vehicle which may injure vulnerable road users.

To remedy the affected vehicles, Polestar will remove any residual masking tape and replace the panoramic glass roof according to VIDA instruction.

Important Note: Before mounting the new panoramic glass roof, please perform the following steps:

- Please ensure that all masking tape residue is removed from the body around the roof area.
- Please ensure that all adhesive bead is removed and the body surface is cleaned and primed before reinstallation.

A total of 19 U.S. vehicles are affected by this recall.

Part Number	Qty	Failing Part	Description
3241608	1	F	Panorama roof
32132748	2		Adhesive kit
31375637	0.2		Cleaner H
32382995	0.2		Primer