


RECALL 25V423 REMEDY INSTRUCTIONS

 FOREST RIVER	Make(s): SPIRIT Model(s): SBT2565FK Model Year(s): 2026	Repair Code: RC-072-01-00-004723 Allotted Time: N/A Inspection Code: N/A Allotted Time: N/A
	Concern: The safety chains may not meet the Gross Vehicle Weight Rating ("GVWR") that is listed on the Federal Placard.	Photo(s) Required: N/A Prior Authorization Required: N/A Part(s) Kit Number: N/A Part(s) Return: N/A

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

LIPPERT COMPONENTS WILL BE PERFORMING THE REMEDY TO REPLACE THE SAFETY CHAINS ON ALL AFFECTED VEHICLES.

- Contact Debra O'Rourke at 574-825-8519 to assist with the scheduling service at your dealership for the remedy.