

Purpose: This guide provides step-by-step instructions for updating the firmware on the RVM-2.0.

Update Addressed: Remedy Pursuant to NHTSA recall 25V535

Note: Speakers will need to be checked for any damage/melting and replaced if necessary.

Requirements:

- Supplied USB drive with the firmware RV620_20250725U2
- Radio with the following firmware: 231201U1

UPDATE INSTRUCTIONS

Step 1 — Power On the System

- Turn on the vehicle.
- Turn on the radio.

Step 2 — Verify Current Firmware

- Press the mode button until the radio is on AUX 1
- Hold the #1 button down for 3 seconds until the current firmware version is displayed.
- If your firmware is **231201U1** continue on to step 3. If your firmware is any other number, turn to the backside of this page.

Step 3 — Start the Update

- Insert the USB drive into the front USB slot.
- The radio will display: "Updating."

IMPORTANT

Do not turn off the radio or vehicle during the update.

Step 4 — Update Process

- The update will take about 2 minutes.
- When complete, the radio display and button lights will turn off.
- Remove the USB drive.
- Press the reset button on the face of the radio.

Step 5 — Factory Reset

- Power the radio back on.
- Switch to AUX 1 source.
- Press and hold the ">>|" button for 5 seconds. This will perform a factory reset.

Step 6 — Confirm Update

- Power the radio back on.
- Switch to AUX 1 source.
- Press and hold the 1 preset button until the firmware version is displayed.

If the version reads:

MPEG SW Version (**250725U2**), the latest firmware has been successfully installed.

Purpose: This guide provides step-by-step instructions for updating the firmware on the RVM-2.0.

Update Addressed: Remedy Pursuant to NHTSA recall 25V535

Note: Speakers will need to be checked for any damage/melting and replaced if necessary.

Requirements:

- Supplied USB drive with the firmware RV620_20250725U1
- Radio with any of the following firmwares. 190428U2, 190629U2, 200616U1, 231115U1

UPDATE INSTRUCTIONS

Step 1 — Power On the System

- Turn on the vehicle.
- Turn on the radio.

Step 2 — Verify Current Firmware

- Press the mode button until the radio is on AUX 1
- Hold the #1 button down for 3 seconds until the current firmware version is displayed.
- If your firmware is any of the following, 190428U2, 190629U2, 200616U1, or 231115U1, continue on to step 3. If your firmware is 231201U1 turn to the backside of this page and follow those instructions.

Step 3 — Start the Update

- Insert the USB drive into the front USB slot.
- The radio will display: "Updating."

IMPORTANT

Do not turn off the radio or vehicle during the update.

Step 4 — Update Process

- The update will take about 2 minutes.
- When complete, the radio display and button lights will turn off.
- Remove the USB drive.
- Press the reset button on the face of the radio.

Step 5 — Factory Reset

- Power the radio back on.
- Switch to AUX 1 source.
- Press and hold the ">>|" button for 5 seconds. This will perform a factory reset.

Step 6 — Confirm Update

- Power the radio back on.
- Switch to AUX 1 source.
- Press and hold the 1 preset button until the firmware version is displayed.

If the version reads:

MPEG SW Version (**250725U1**), the latest firmware has been successfully installed.