

Parts Bulletin

TITLE:

Recall RP1064: Model Year 2025 Polestar 3 Hood Wing

GROUP:

86

NO:

RP1064

CAR MARKET:

United States

REVISIONS:

ISSUE DATE:

2025-08-26

STATUS DATE:

2025-08-26**Page 1 of 1****Reference Bulletins: QB RP1064**

Polestar Automotive USA, on behalf of Polestar Performance AB, have decided to launch Recall RP1064 on certain model year 2025 Polestar 3 vehicles.

Polestar has identified that the hood wing may have been incorrectly attached to the front bumper during manufacturing.

As a result, the hood wing may detach and separate from the vehicle while driving increasing the risk of a crash.

To remedy the affected vehicles, Polestar will inspect the hood wing and if any screws are found to be missing, the hood wing will be replaced, and the missing screws will be installed.

A total of 68 U.S. Vehicles is affected by this recall.

The following part numbers apply:

Part Number	Qty	Failing Part	Description
31 109 339	6		Six point socket screw
40 008 105	1	F	Panel