



NHTSA:25V-673

TransportCanada:TC2025-537

Winnebago Towable: CAM0000044

**TO: Winnebago Towables Dealers**

**SUBJECT: Bedroom Shelf May Fail due to Improper Securement**

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. As you will see in reading the enclosed copy of the letter, which is being sent to owners, the owners are being instructed to contact Winnebago Industries, Inc. if you do not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

#### **REASON FOR THIS RECALL**

Winnebago of Indiana has decided that a defect which relates to motor vehicle safety exists on certain 2025 and 2026 Access models. These vehicles were manufactured **December 26, 2024**, through **May 2, 2025**.

On certain Winnebago vehicles the shelf above the bed may have been installed incorrectly, which can allow the shelf to detach. A shelf that detaches can hit an occupant increasing the risk of injury

#### **OWNER NOTIFICATION**

Owners will be notified of this campaign on their vehicles by Winnebago Towables. For all units in your inventory, the notification will be mailed to you. **DO NOT DELIVER TO A CUSTOMER ANY SUBJECT UNIT UNTIL CORRECTIVE ACTION HAS BEEN TAKEN.**

#### **DEALER CAMPAIGN RESPONSIBILITY**

Dealers are to service all vehicles subject to this campaign at no charge to owners regardless of mileage, age of vehicle, or ownership from this time forward. Whenever a vehicle subject to this campaign is taken into new or used vehicle inventory or it is in your dealership for service in the future, you should take the steps necessary to be sure the campaign correction has been made before reselling or releasing the vehicle. Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this campaign.

201 14<sup>th</sup> Street, Middlebury, In 46540  
Phone: 574-825-8052, [wtowWarrantyTech@winnebagoind.com](mailto:wtowWarrantyTech@winnebagoind.com)  
Winnebago.com



**NHTSA:25V-673**

**TransportCanada:TC2025-537**

**Winnebago Towable: CAM0000044**

Safety Recall:

Bedroom Shelf May fall due to Improper Securement

**Repair, Claim Preparation, and Filing Instructions**

Please submit a warranty claim pre-authorization using the following codes and labor times:

<b>LABOR:</b>	<b>OPERATION CODE</b>	<b>LABOR ALLOWANCE</b>
---------------	-----------------------	------------------------

<b>Inspect &amp; Install:</b>	<b>44019704</b>	<b>0.3 hours</b>
-------------------------------	-----------------	------------------

**PARTS: 287607 Shelf Stile 0.75x0.75x17 Order 2 per unit.**

Please follow attached repair instructions.


Submit all pre-authorizations and claims through the Dealer Portal. If there are any questions, please call our Warranty Team at 574-825-8052.

Safety Recall:

Bedroom Shelf May fall due to Improper Securement

**Tools Needed:**

- **Screw gun**
- **#8 Truss Head Coarse Thread Self-Tapping 1.25” Screws**



**Repair Instructions:**

- 1. Inspect the shelf to ensure that it is secured to the top cleat, the sidewall, and RHF wardrobe**



- 2. Install 3 screws into the top stile going into the shelf and into the off-doorside sidewall. Then install 3 screws going into the shelf from the top of the stile.**

201 14<sup>th</sup> Street, Middlebury, In 46540  
Phone: 574-825-8052, [wtowWarrantyTech@winnebagoind.com](mailto:wtowWarrantyTech@winnebagoind.com)  
Winnebago.com

- 3. Install cleat on the bottom of the left side of the shelf, securing with 3 screws into the sidewall backer and 3 screws going up into the shelf.**



- 4. Repeat on the right side. Secure the cleat to the bottom side of the shelf and into the backer in the wardrobe.**

