



Thor Motor Coach Recall Repair Instructions

Recall #	25V-709 2025-570		
Description/Title:	Generator Exhaust		
Affected Product Line(s):	Certain MY 2025-2026 Chateau, Coleman, Echelon, Eddie Bauer, Four Winds, Freedom Elite, Geneva, Pasadena, Quantum		
Service Campaign # :	RC000335		
Repair Code:	Inspect with Repair: TMCRC10121V	Document Date:	12/15/2025
Time Allowed:	Inspect with Repair: 0.4	Document Revision:	A

Issue:

It has been discovered that p-clamps may be missing allowing the fuel hose and/or wire harnesses to rest on the generator exhaust.

Parts:

Repair kit: 0598063


Instructions:

1. Inspect generator exhaust for any fuel hose or wire harnesses making contact.

Examples:



Thor Motor Coach Recall Repair Instructions



2. If any fuel hose or wire harness is damaged, replace it prior to proceeding. ***This is not part of the recall and will need to be submitted to TMC as a separate repair claim***

Thor Motor Coach
1-877-500-1020
NHTSA Recall # 25V-709
Transport Canada Recall # 2025-570




Thor Motor Coach Recall Repair Instructions

3. Find the union for the generator fuel line.



4. Clamp the fuel hose on the fuel tank side of the union to prevent fuel spillage. Separate the fuel hose at the union.



5. Install the heat sleeve onto the fuel hose leading towards the generator, then resecure the fuel hose to the union.



6. Use the supplied p-clamps to hold the fuel hose and any necessary wire harness away from the generator exhaust. Examples:

Thor Motor Coach
1-877-500-1020
NHTSA Recall # 25V-709
Transport Canada Recall # 2025-570



Thor Motor Coach Recall Repair Instructions

