


## RECALL 25V728. 2025-582 REMEDY INSTRUCTIONS

 <b>FOREST RIVER</b>	Make(s): CATALINA Model(s): CAT194RBS Model Year(s): 2026	Repair Code: RC-004-09-00-004765 Allotted Time: .25 HRS. Inspection Code: N/A Allotted Time: N/A
	Concern: Under jounce, the tire may contact the chassis outrigger on the road side of the vehicle.	Photo(s) Required: NO Prior Authorization Required: YES Part(s) Kit Number: N/A Part(s) Return: N/A

**Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.**

STEP 1: LOCATE THE OUTRIGGER ON THE ROADSIDE OF THE VEHICLE, ON THE FORWARD SIDE OF THE TIRE;

- NOTICE IT HAS LITTLE TIRE CLEARANCE;

STEP 2: MEASURE 3 1/2" UP FROM THE TIRE, VERTICALLY, MARK THE ENTIRE DEPTH OF THE OUTRIGGER;

- MARK FROM WHERE THE OUTRIGGER MOUNTS TO THE FLOOR TO THE MAIN BEAM;

STEP 3: USING A CUTTING DEVISE, TRIM THE OUTRIGGER ALONG THE MARKINGS MADE;

STEP 4: MEASURE THE VERTICAL DISTANCE FROM THE TIRE TREAD TO THE TRIMMED OUTRIGGER;

- THIS SHOULD NOW BE 3 1/2";
- ENSURE CLEARANCE IS ADEQUATE FROM THE INSIDE TIRE WALL TO THE OUTRIGGER AS WELL;

STEP 5: USE GRINDER TO SMOOTHEN ANY SHARP EDGES OF THE TRIMMED OUTRIGGER;

STEP 6: ENSURE PROPER CLEARANCE;

STEP 7: CLAIM REPAIR CODE.