



July, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2020 Corsair has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **25S05 - Rear-View Camera Improper Function - Replacement**

What is the issue? On your vehicle, the rear-view camera could have intermittent rearview video image, no rearview video image, or poor image quality (Blurry, Foggy, Hazy) when the vehicle is in reverse gear.

A rear-view camera that intermittently displays a blank or distorted image may reduce the driver's view of what is behind the vehicle, increasing the risk of a crash.

If you have questions or concerns, please contact our **Lincoln Recall Assistance Center (RAC)** at **1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Julio de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

Según nuestros registros, no se realizaron en sur 2020 Corsair las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **25S05 - Funcionamiento incorrecto de la cámara trasera**

¿Cuál es el problema? En su vehículo, la cámara trasera podría tener una imagen de video trasera intermitente, podría no tener ninguna imagen de video trasera o bien tener una calidad de imagen deficiente (borrosa, nublada, brumosa) cuando el vehículo está en reversa.

Cuando una cámara trasera, de forma intermitente, aparece en blanco o muestra una imagen distorsionada, la vista que tiene el conductor de lo que hay detrás del vehículo podría verse reducida, lo cual aumenta el riesgo de sufrir un choque.

Si tiene preguntas o inquietudes, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Lincoln al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es Lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.



L I N C O L N

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0060722 A / 000000000000507 / 37



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

