



August, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2022 Transit has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: 25S23 - 2022-23 TRANSIT - 22S65 Software Remedy Audit - Safety

What is the issue? According to Ford's records, the remedy software for 22S65 may not have been installed correctly during a prior dealership visit. Because the correct software may not have been installed on your vehicle, the underlying condition specified in Safety Recall 22S65 may still exist. On your vehicle, the heating, ventilation, and air-conditioning (HVAC) system's controls, including defog and defrost, may become inoperative.

Loss of the ability to control the vehicle's defrost or defog function may decrease the driver's visibility under certain driving conditions, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Augusto de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2022 Transit las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 25S23 - TRANSIT 2022-23 - 22S65 Auditoría de corrección de software - Seguridad

¿Cuál es el problema? Según los registros de Ford, es posible que el software de solución para 22S65 no se haya instalado correctamente durante una visita anterior al concesionario. Debido a que es posible que no se haya instalado el software correcto en su vehículo, la condición subyacente especificada en la Campaña de seguridad 22S65 podría existir todavía. En su vehículo, los controles del sistema de calefacción, ventilación y aire acondicionado (HVAC), incluidos el desempañador y el descongelador, podrían dejar de funcionar.

La pérdida de la capacidad de controlar la función de descongelación o desempañado del vehículo puede disminuir la visibilidad del conductor en determinadas condiciones de conducción, lo que aumenta el riesgo de accidente.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atención en este asunto sumamente importante.

1 of 2

00000000000778 / 1555 / 778



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C


0062559 A / 000000000000778 / 778



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶



▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶