



August, 2025

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2025 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **25S29 - 2025 F150 - FHEV Battery BEC 60 Amp Fuse Concern - Safety**

What is the issue? On your vehicle, the high current fuse, located in the High Voltage Battery Junction Box, has an incorrect amperage rating for the application.

A high current fuse with an incorrect amperage rating may blow, which can result in a sudden loss of motive power if the vehicle is operating in electric-only mode. A loss of motive power increases the risk of a crash.

If you have questions or concerns, please contact our **Ford Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

Augusto de, 2025

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2025 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **25S29 - F150 2025 - Problema con el fusible de 60 amperes del BEC de la batería del FHEV - Seguridad**

¿Cuál es el problema? En su vehículo, el fusible de alta corriente, ubicado en la caja de conexiones de la batería de alto voltaje tiene un amperaje incorrecto para la aplicación.

Un fusible de alta corriente que tenga un amperaje incorrecto se puede fundir, y esto puede provocar una pérdida repentina de potencia motriz si el vehículo está funcionando solo en modo eléctrico. Una pérdida de fuerza motriz aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.


Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0521342 A / 000000000000833 / 833



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶
REMOVE THESE SIDE EDGES FIRST

