



February, 2026

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2025 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **25C33 - Coordinated Module Software Update**

What is the issue? On your vehicle, the rear side windows may exert excessive force when closing against any part of a person or object in the window opening before automatically reversing. This can occur if the Global Close Lincoln feature is activated using the key fob or the LincolnWay mobile applications.

A window automatic reversal system that exerts excessive force before automatically reversing increases the risk of injury.

If you have questions or concerns, please contact our **Lincoln Recall Assistance Center (RAC) at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Febrero de, 2026

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2025 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **25C33 - Actualización de software del módulo coordinado**

¿Cuál es el problema? En su vehículo, las ventanas laterales traseras pueden ejercer una fuerza excesiva al cerrarse contra cualquier parte de una persona u objeto en la abertura de la ventana antes de revertirse automáticamente. Esto podría ocurrir si se activa la función Global Close Lincoln a través del llavero transmisor o mediante las aplicaciones móviles LincolnWay.

Un sistema de inversión automática de ventanas que ejerce una fuerza excesiva antes de invertirse automáticamente aumenta el riesgo de sufrir lesiones.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de asistencia de campañas (RAC) Lincoln al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.



L I N C O L N

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

0539358 A / 000000000000886 / 21



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

