

SEPTEMBER 2025

IMPORTANT SAFETY RECALL 25509

INTERIM NOTICE

NHTSA RECALL NO. 25V502

THIS NOTICE APPLIES TO YOUR VEHICLE IDENTIFIED ON THE ENCLOSED CARD.

Dear International Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

International Motors, LLC* has decided that a defect which relates to motor vehicle safety exists in certain 2018 thru 2025 International® MV® Series trucks built 10/25/2017 thru 6/24/2024 , 2018 thru 2024 International® 1300 Series trucks built 11/29/2017 thru 6/14/2023 and 2018 thru 2019 International® 4300 Series trucks built 9/20/2017 thru 1/9/2019, with feature codes 0004198, 0004240 (Brake system, hydraulic with Hydromax brake booster). Model specific data below:

If you are the lessor of this vehicle, please forward a copy of this notice to the lessee within ten days to comply with federal regulations.

If you do not own this vehicle, please fill out and return mail the enclosed card so that you will not be contacted again about this recall.

IF YOU NEED FURTHER ASSISTANCE

Refer to the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825. International Motors, LLC requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

REASON FOR THIS RECALL

The brake pressure switch may allow brake fluid to seep past the diaphragm seal into the brake pressure switch electrical connector and associated fuse which can short the switch and/or fuse.

RISK TO MOTOR VEHICLE SAFETY

A shorted switch or fuse may cause the circuit to generate excessive heat which can result in a fire, increasing the risk of property damage or personal injury to the operator.

DEFECT REMEDY

You may already have been contacted about a similar Safety Recall 23517 (NHTSA 23V-397) in 2023. Any vehicle remedied under that recall also requires this recall remedy to be performed.

A final remedy has been determined. Parts are on order, but availability is currently unknown. A second notice will be sent to you, once the free remedy is available.

ACTIONS YOU SHOULD TAKE

Until the remedy can be performed, vehicle owners are advised to park their vehicles outdoors.