

06 SAFETY RECALL N972 – TOUCHSCREEN BLANK ON START-UP

SAFETY RECALL N972 TOUCHSCREEN BLANK ON START-UP	
AFFECTED MODELS / PART NUMBER	23MY Range Rover Evoque and Discovery Sport 23–24MY Defender
VOLUME AFFECTED	28,370 USA 2,950 CAN
REPAIR	Certain vehicles with a 10-inch Touchscreen may experience a blank screen on start-up and throughout the drive cycle. Multiple vehicle modules require TOPIx software updates.  The software fix will also be included in upcoming SOTA campaign S028 4.3.0
REPAIR TIME	Up to 1.1 hrs + DIDO
CAMPAIGN LAUNCH	January 29th, 2025
NOTES	Retailers are instructed to hold and not sell or deliver any affected vehicles under their control until the recall repair has been completed. Sold vehicles must be repaired at the next service visit. As of February 3rd, there are 276 US, and 1 CAN affected vehicles in retailer unsold new inventory.  Clients will be notified via mail on or before March 14th, 2025.