

RECALLS N978/N979 – PASSENGER/DRIVER LOWER AIRBAG MODULE - RENEW

SAFETY RECALL N978/N979 - PASSENGER/DRIVER LOWER AIRBAG MODULE - RENEW

AFFECTED MODELS	20MY RANGE ROVER EVOQUE
VOLUME AFFECTED	PASSENGER LOWER AIRBAG N978 – US 1,473 CAN 393 DRIVER LOWER AIRBAG N979 – US 1269 CAN 326
REPAIR	A concern has been identified with certain vehicles where the driver or passenger lower airbag module cushion cover may become loose due to a degradation of the adhesive on the driver and/or passenger lower airbag module dust cover. Replacement airbag/s will be required.
REPAIR TIME	0.2 hrs. + DIDO for a single airbag replacement
CAMPAIGN LAUNCH	Retailer notification on February 27th, 2025. Recall launched on May 29th, 2025
NOTES	Owners were notified via interim mailing on April 11th, 2025. Another mailing will now be sent to inform owners that the recall repair is available.  An initial batch of parts will be ordered and allocated to all retailers by JLRNA Parts teams, For more information, please refer to USA Parts bulletins 252605.047 & 252605.048 published May 30th and in Canada, JLRCS2506.02 & JLRCS2506.03.