

H552/N945 – PASSENGER FRONTAL AIRBAG REPLACEMENT

SAFETY RECALL



AFFECTED MODELS	21-24MY E-PACE 21-25MY Range Rover Evoque
VOLUME AFFECTED	H552 - 1436 USA 95 CAN N945 - 20999 USA 3115 CAN
REPAIR	A concern has been identified on certain vehicles where, during a passenger airbag deployment, the airbag may tear as a result of improper folding of the airbag during the airbag assembly process. A replacement passenger airbag will be required.
REPAIR TIME	1.1 hrs + DIDO
CAMPAIGN LAUNCH	Retailers were notified by Recall Admin Bulletins N945ADM1 and H552ADM1 (July 16th, 2025.) H552 (JAGUAR) repair was launched on November 28th, 2025 N945 (LAND ROVER) launch is expected w/c January 12th 2026
NOTES	Retailers are required to hold all affected new vehicles in their inventory from sale until the repair is available and completed. Please refer to recall bulletin for instructions on used vehicles in retailer inventory. All affected VINs are flagged in TOPIx and the warranty portal. <u>Please refer to Customer Service Parts Operations Bulletins 252611.038 - USA and JLRCS2511.07 – Canada, published November 25th, 2025, for details of Jaguar E-PACE airbags that have been pre-shipped to retailers.</u>