



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

**1200 New Jersey Avenue SE
Washington, DC 20590**

August 21, 2026

26E058

Sarah Apple
Holley Performance Products
1801 Russellville RD
Bowling Green, KY 42101

Subject: Loss of Throttle Control

Dear Sarah Apple:

This letter serves to acknowledge Holley Performance Products's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Brand/Model/Part Number:

HOLLEY/AVENGER CARBURETOR
HOLLEY/STREET AVENGER CARBURETOR
HOLLEY/CLASSIC CARBURETOR
HOLLEY/QUICKFUEL CARBURETOR
HOLLEY/SUMMIT CARBURETOR
HOLLEY/THROTTLE BODY KIT
HOLLEY/MARSHALL CARBURETOR

Mfr's Report Date: August 17, 2026

NHTSA Campaign Number: 26E058

Components:

FUEL SYSTEM, GASOLINE:CARBURETOR SYSTEM

Potential Number of Units Affected: 4,496

Problem Description:

Holley Performance Products (Holley) is recalling certain Replacement Carburetors and Throttle body kits. Please see the attached document for a complete list of models and part numbers. The secondary vacuum throttle levers may be undersized, possibly causing interference with the primary/secondary shaft and leading to a loss of throttle control.

Consequence:



A loss of throttle control increases the risk of a crash.

Remedy:

Holley will work with owners to replace the carburetors, free of charge. Owner notification letters are expected to be mailed September 11, 2026. Owners may contact Holley Customer service at 1-800-638-0032.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Holley Performance Products's contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement