



U.S. Department of Transportation

**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

January 28, 2026

26V043

Dennis Carl
Brinkley RV
1655 Brinkley Way East
Goshen, IN 46528

Subject: Improperly Tightened 50-Amp Shore Power Inlet May Cause Fire

Dear Dennis Carl:

This letter serves to acknowledge Brinkley RV's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BRINKLEY RV/MODEL Z/2026

Mfr's Report Date: January 23, 2026

NHTSA Campaign Number: 26V043

Components:

ELECTRICAL SYSTEM

Potential Number of Units Affected: 48

Problem Description:

Brinkley RV (Brinkley) is recalling certain 2026 Model Z trailers. The shore power inlet lugs may have been improperly tightened.

Consequence:

The wires may loosen and overheat, increasing the risk of a fire.

Remedy:

Dealers will inspect and properly tighten the lugs as necessary, free of charge. Owner notification letters are expected to be mailed January 30, 2026. Owners may contact Brinkley's customer service at 1-574-501-4280. Brinkley's number for this recall is REC-2601.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

We have received your proposed owner notification letter and it is approved for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Brinkley RV's contact for this recall will be Hensly Guerra who may be reached by email at hensly.guerra1@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement