



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

**1200 New Jersey Avenue SE
Washington, DC 20590**

July 22, 2026

26V438

Martin Rapaport
BMW of North America, LLC
PO Box 1227
200 Chestnut Ridge Road
Westwood, NJ 07675-1227

Subject: Starter Motor May Overheat and Cause a Fire

Dear Martin Rapaport:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/X3/2021-2022, 2024
BMW/X4/2021-2025
BMW/530I/2021-2023
BMW/Z4/2022-2026
TOYOTA/SUPRA/2023-2024
BMW/230I/2022-2025
BMW/430I/2023-2024
BMW/330I/2023-2024
BMW/230I XDRIVE/2022-2025
BMW/430I XDRIVE/2023-2024
BMW/330I XDRIVE/2023-2024
BMW/530I XDRIVE/2021-2023

Mfr's Report Date: July 08, 2026

NHTSA Campaign Number: 26V438

Components:

ELECTRICAL SYSTEM:STARTER ASSEMBLY

Potential Number of Units Affected: 318,495

Problem Description:

BMW of North America, LLC (BMW) is recalling certain 2023-2024 Toyota Supra, 2022-2025 2 Series Coupe, 2021-2023 5 Series, 2022-2026 Z4, 2023-2024 4 Series Gran Coupe, 4 Series Convertible, 4 Series Coupe, 3 Series, 2021-2025 X4, and 2021-2024 X3 vehicles. Please see the recall report for a complete list of all models. The engine starter may overheat and catch fire due to wear on an internal component.

Consequence:

Fire increases the risk of injury.

Remedy:

Dealers will replace the engine starter, free of charge. Owner notification letters are expected to be mailed on August 28, 2026. Owners may contact BMW customer service at 1-800-525-7417 or Toyota's customer service at 1-800-331-4331. Vehicle Identification Numbers (VINs) involved in this recall will be searchable on NHTSA.gov beginning August 28, 2026. This recall is an expansion of previous NHTSA recall 26V056.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

Reimbursement Plan Not Supplied

Provide a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers, and dealers, in accordance with 49 CFR 573.13. Your company's plan may incorporate by reference a general reimbursement plan previously submitted to NHTSA, together with information specific to the individual recall. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (49 CFR 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the reimbursement section of an amended Part 573 Recall Report through the NHTSA Recalls Portal.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

BMW of North America, LLC's contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement