



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

**1200 New Jersey Avenue SE
Washington, DC 20590**

August 19, 2026

26V527

John Kobylarz
Jaguar Land Rover North America, LLC
100 Jaguar Land Rover Way
Mahwah, NJ 07495

Subject: Incorrect Front Suspension Knuckles Installed

Dear John Kobylarz:

This letter serves to acknowledge Jaguar Land Rover North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

LAND ROVER/RANGE ROVER/2016-2017

Mfr's Report Date: August 13, 2026

NHTSA Campaign Number: 26V527

Components:

STEERING:LINKAGES:KNUCKLE:SPINDLE:ARM

Potential Number of Units Affected: 14

Problem Description:

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2016-2017 Range Rover vehicles. The front suspension knuckles may have been replaced with incorrect parts during a prior recall remedy repair.

Consequence:

An incorrect suspension knuckle may not perform as expected, possibly resulting in a loss of vehicle handling and control, increasing the risk of a crash.

Remedy:

Dealers will replace the front suspension knuckles, free of charge. Interim letters notifying owners of the safety risk are expected to be mailed October 9, 2026. Additional letters will be sent once the final



remedy is available. Owners may contact Land Rover's customer service at 1-800-637-6837. Land Rover's number for this recall is D148.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-888-275-9171), or go to www.nhtsa.gov.

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Jaguar Land Rover North America, LLC's contact for this recall will be Debora Crews who may be reached by email at debora.crews@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement