



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

# Part 573 Safety Recall Report

26V034

**Manufacturer Name:** Hyundai Motor America

**Submission Date:** Jan 22, 2026

**NHTSA Recall No.:** 26V034

**Manufacturer Recall No.:** 292

## Manufacturer Information

## Population

**Manufacturer Name:** Hyundai Motor America  
**Address:** 10550 Talbert Avenue  
Fountain Valley CA, 92708

**Total number of potentially involved:** 568,576  
**Estimated percentage with defect:** 100%

## Vehicle Information

**Vehicle 1:** 2020-2025 HYUNDAI PALISADE

**Product Category:** Light Vehicles

**Product Type:** Multipurpose Passenger Vehicle

**Fuel / Propulsion:** Spark Ignition Fuel

**Production Dates:** Apr 10, 2019 - Jun 16, 2025

**Number of potentially involved:** 568,576

### Descriptive Information:

Based on manufacturing records, certain model year 2020-2025 Hyundai Palisade vehicles produced on the specified dates by Hyundai Motor Company ("HMC") for sale in the U.S. are affected.

## Defect / Noncompliance Description

### Description of the defect or noncompliance:

The subject vehicles may not meet the allowable third row headform displacement requirements set forth in Federal Motor Vehicle Safety Standard ("FMVSS") No. 226, "Ejection Mitigation."

**FMVSS1:** 226 - Ejection mitigation

**FMVSS2:**

### Description of the safety risk, including crash, fire, death, injury:

A vehicle that fails to comply with this standard might have increased risk of injury to third row occupants during certain crashes including a rollover.

### Description of the cause:

# Part 573 Safety Recall Report

26V034

Hyundai's investigation is ongoing.

## Identification of any warning that can occur:

None.

## Component Manufacturer

**Tier of Supplier:** Tier 1

**Supplier Type:** OEM

**Name:** AUTOLIV

**Address:** 730-66, Dongbu-daero  
Hwaseong City  
Gyeonggido Foreign States

**Country:** Korea, Republic Of

## Involved Components

**Component Name 1:** Module Curtain Airbag

**Component Description:** Palisade LH specification

**Component Part Number:** 80410-S8500

**Component Name 2:** Module Curtain Airbag

**Component Description:** Palisade RH specification

**Component Part Number:** 80420-S8500

## Chronology

### April - November 2025

Hyundai was informed by the National Highway Traffic Safety Administration (NHTSA) of the results from a routine Federal Motor Vehicle Safety Standard (FMVSS) No. 226 compliance test conducted by MGA on a model year 2025 Palisade vehicle. According to NHTSA, the measured displacement of the ejected headform in the third-row seating area exceeded the 100 mm performance limit specified in the standard.

In response, Hyundai initiated an investigation in coordination with NHTSA's Office of Vehicle Safety Compliance (OVSC) and the Hyundai America Technical Center, Inc. (HATCI). Between July and November 2025, the parties conducted multiple inspections, technical assessments, and engineering

# Part 573 Safety Recall Report

26V034

reviews. On November 5, 2025, NHTSA performed a re-test using an exemplar vehicle, which produced results consistent with those recorded during the initial April test.

## December 2025 - January 2026

Beginning on December 8, 2025, Hyundai conducted its own FMVSS No. 226 compliance tests in cooperation with MGA to replicate the results of NHTSA's November re-test, using vehicles across multiple trim levels. In certain instances, the testing produced third-row ejection headform displacement values that exceeded the 100 mm performance limit specified in the standard.

Hyundai shared these test results with the Office of Vehicle Safety Compliance (OVSC) in December 2025 and subsequently provided additional analysis—including curtain shield airbag reviews and test video evaluations conducted by the airbag supplier, Autoliv—on January 8, 2026.

## January 14, 2026

Based on the December test results and the supplier analyses received in January, NASO convened its North America Safety Decision Authority ("NASDA"). Following its review, NASDA determined that a defect condition exists in the subject vehicles that results in noncompliance with FMVSS No. 226. Accordingly, NASDA concluded that a noncompliance recall is warranted for potentially affected vehicles in the U.S. market.

## Related NHTSA Recall Number:

## Description of Remedy

### Remedy Type:

**Consumer Advisories:**  Do Not Drive  Park Outside

### Description of remedy program:

Hyundai is currently developing a remedy for this condition. When available, this remedy will be offered at no cost to owners for all affected vehicles, regardless of whether the affected vehicles are still covered under Hyundai New Vehicle Limited Warranty. Additionally, Hyundai will provide owners of affected vehicles reimbursement for out-of-pocket expenses incurred to obtain a remedy for the recall condition in accordance with the reimbursement plan submitted to NHTSA on February 22, 2024.

### How remedy component differs from recalled component:

Information to be provided when a remedy is finalized.

### Identify how/when recall condition was corrected in production:

The affected vehicles are no longer in production.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

# Part 573 Safety Recall Report

26V034

## Recall Schedule

**Description of recall schedule:**

Dealers will be notified electronically by the specified dates.  
Owners will be notified via certified mail by the specified dates.

**Planned Dealer Notification Date:** Mar 23, 2026 - Mar 23, 2026

 No Dealers

**Planned Interim Owner Notification Date:**

 No Owners

**Planned Remedy Owner Notification Date:** Mar 23, 2026 - Mar 23, 2026

 Phased Recall

**Date when VIN will be searchable:** Jan 24, 2026