



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 26V045

**Manufacturer Name:** Keystone RV Company

**Submission Date:** Jan 26, 2026

**NHTSA Recall No.:** 26V045

**Manufacturer Recall No.:** 26-479

### Manufacturer Information

### Population

**Manufacturer Name:** Keystone RV Company

**Address:** PO Box 2000  
2642 Hackberry Drive  
Goshen IN, 46527

**Total number of potentially involved:** 115

**Estimated percentage with defect:** 100%

### Vehicle Information

**Vehicle 1:** 2026-2026 Keystone Coleman

**Product Category:** Trailers

**Product Type:** Recreational Trailers

**Fuel / Propulsion:**

**Production Dates:** Aug 21, 2025 - Jan 07, 2026

**Number of potentially involved:** 115

**Descriptive Information:**

Model(s): Coleman 13T, Floorplans that use 54" x 74" murphy beds.

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

It has been decided that the vehicles in the recall population may have murphy beds with insufficient securement of the bed brackets to the wall.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

Under certain conditions when the murphy bed is in the vertically stored position, the bed brackets may pull free from the wall leading to an increased risk of personal injury.

**Description of the cause:**

# Part 573 Safety Recall Report

# 26V045

The murphy bed bracket holes are misaligned with the exterior wall stud.

## Identification of any warning that can occur:

The murphy bed wall brackets may appear loose, or screws may pull out from the wall brackets.

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

## Involved Components

**Component Name 1:** Frame - Murphy Bed - 54" x 74" - LPMWBA - w/15.75"

**Component Description:** Murphy Bed - 54" x 74"

**Component Part Number:** 780654

## Chronology

01/07/2026 – Report was made

01/07/2026 – Investigation opened. All affected units not shipped were put on hold and inspected and repaired.

01/12/2026 – Warranty claims for bed hardware securement include 13 claims, claim created start date 12/22/2025 to claim created end date 01/12/2026

01/20/2026 – Keystone Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall. Investigation called for to determine affected unit range.

01/20/2026 – Investigation concluded and scope completed.

**Related NHTSA Recall Number:**

## Description of Remedy

# Part 573 Safety Recall Report

# 26V045

## Remedy Type:

**Consumer Advisories:**  Do Not Drive  Park Outside

## Description of remedy program:

The remedy is to identify the location of the wall studs or backers and secure the bed wall brackets at the proper location.

## How remedy component differs from recalled component:

No parts will be replaced. The repair is to secure the components to the correct location.

## Identify how/when recall condition was corrected in production:

Units were quarantined, inspected then repaired as indicated by inspection.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

### Description of recall schedule:

Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

**Planned Dealer Notification Date:** Mar 19, 2026 - Mar 19, 2026  No Dealers

**Planned Interim Owner Notification Date:**  No Owners

**Planned Remedy Owner Notification Date:** Mar 19, 2026 - Mar 19, 2026  Phased Recall

**Date when VIN will be searchable:** Mar 19, 2026