



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V052

Manufacturer Name: Winnebago Towable

Submission Date: Jan 29, 2026

NHTSA Recall No.: 26V052

Manufacturer Recall No.: 44448204

Manufacturer Information

Population

Manufacturer Name: Winnebago Towable

Address: 201 14th Street
Middlebury IN, 46540

Total number of potentially involved: 100

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 Winnebago Access

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Aug 29, 2025 - Oct 31, 2025

Number of potentially involved: 100

Descriptive Information:

The recall population was determined by pulling VIN information.

Defect / Noncompliance Description

Description of the defect or noncompliance:

Certain Winnebago vehicles do not meet the requirements of the Federal Motor Vehicle Safety Standard 49 CFR 567 due to missing GAWR information on the certification labels.

FMVSS1: 567 - Certification

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The absence of GAWR on the certification label may lead to improper axle loading, which could increase the risk of tire overloading, reduced braking performance, or loss of vehicle control.

Description of the cause:

Part 573 Safety Recall Report

26V052

The system contained inaccurately entered information

Identification of any warning that can occur:

N/A

Component Manufacturer

Tier of Supplier:

Supplier Type: OEM

Name: Winnebago of Indiana

Address: 201 14th St
Middlebury IN, 46540

Country: United States

Involved Components

Component Name 1: Label-Federal Tag 4"x7.7"

Component Description: Label-Federal Tag 4"x7.7"

Component Part Number: 287015

Chronology

In early December Product Safety was notified by a dealer partner regarding a non-compliance; the Information Placard was missing the GAWR. Subsequently, Product Safety opened an investigation. On January 22nd, 2026, the Product Safety Committee met to review the investigation and determined a non-compliance concern and initiated the recall process.

Winnebago is aware of 8 claims related to this non-compliance. There are no known accidents or injuries related to this issue.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Part 573 Safety Recall Report**26V052**

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How remedy component differs from recalled component:

Winnebago will authorize dealership, or retail customers, to install the new Federal Identification Label and Tire Loading Information Placard

Identify how/when recall condition was corrected in production:

The Federal Identification Label and Tire Loading Information Placard has been corrected in the system.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule**Description of recall schedule:**

The recall schedule will follow the 60-day requirement.

Planned Dealer Notification Date: Feb 27, 2026 - Feb 27, 2026 No Dealers

Planned Interim Owner Notification Date: No Owners

Planned Remedy Owner Notification Date: Mar 19, 2026 - Mar 19, 2026 Phased Recall

Date when VIN will be searchable: