



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V053

Manufacturer Name: Lamborghini (Automobili Lamborghini)

Submission Date: Jan 29, 2026

NHTSA Recall No.: 26V053

Manufacturer Recall No.: L74X-R.01.26

Manufacturer Information

Population

Manufacturer Name: Lamborghini (Automobili Lamborghini)
Address: Via Modena 12
Sant'Agata Bolognese (BO)
40019 - Italy FS, 99999

Total number of potentially involved: 7
Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2025 LAMBORGHINI REVUELTO

Product Category: Light Vehicles

Product Type: Passenger Car

Fuel / Propulsion: Plug-In Hybrid

Production Dates: Sep 14, 2025 - Sep 29, 2025

Number of potentially involved: 5

Descriptive Information:

The recall population was determined by production records.

The recalled products are equipped with certain software versions that may lead to a malfunction.
Vehicles not included do not meet these criteria.

Vehicle 2: 2024-2024 LAMBORGHINI REVUELTO

Product Category: Light Vehicles

Product Type: Passenger Car

Fuel / Propulsion: Plug-In Hybrid

Production Dates: Apr 03, 2024 - Apr 03, 2024

Number of potentially involved: 2

Descriptive Information:

The recall population was determined by production records.

Part 573 Safety Recall Report

26V053

The recalled products are equipped with certain software versions that may lead to a malfunction. Vehicles not included do not meet these criteria.

Defect / Noncompliance Description

Description of the defect or noncompliance:

When the driver quickly shifts into Reverse within one second right after turning the engine OFF/ON (without the car going to sleep), a software issue may prevent the rearview camera image from displaying.

FMVSS1: 111 - Rear visibility

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

A rearview camera image that does not display decreases the driver's visibility, increasing the risk of a crash.

Description of the cause:

Due to a software error, during the specific restart scenario, the ECU which manages the rear view camera may exit the camera display logic.

Identification of any warning that can occur:

If this occurs, the driver will notice the rearview camera image is not displayed. Owners who may experience this issue are advised to use extra caution when reversing, and they should contact an authorized Lamborghini dealer without delay to have the vehicle diagnosed.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: Software for the control unit of driver assistance

Component Description: Software for the control unit of driver assistance systems

Part 573 Safety Recall Report

26V053

Component Part Number:

Chronology

May 2025: During internal testing activities, Lamborghini identified on an internal vehicle, a possible condition in which the rearview camera image was not displaying in the infotainment system. Lamborghini started an investigation in order to assess the influencing factors and possible related hardware and software configurations. No cases or complaints were received from the field so far.

From May 2025 to December 2025: Lamborghini monitored the field while performing technical analysis to identify the root cause.

January 2026: The technical analysis confirmed that on one specific software version and car configuration, the ECU which manages the rear view camera may exit the camera display logic in a certain use scenario, preventing the rearview camera image from displaying. Further investigation was carried out to identify the number of vehicles in the field with the software version and configuration affected.

January 22, 2026: The Lamborghini Product Safety Committee determined that the issue constitutes a noncompliance in the United States and decided a noncompliance recall.

Lamborghini is not aware of any crashes, injuries or property damage complaints related to this issue.

Date of determination: January 22, 2026

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Software

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Automobili Lamborghini S.p.A. will notify all owners of affected vehicles and will instruct them to arrange for an appointment with an authorized Lamborghini dealer. Dealers will update the rear view camera software with a new improved version, free of charge.

How remedy component differs from recalled component:

The software solution has an improved management performance, thereby preventing the failure.

Identify how/when recall condition was corrected in production:

A new software version was introduced in production with the model year 2026 vehicles. This version has an improved management performance which does not present the issue.

Part 573 Safety Recall Report

26V053

Reimbursement Plan

Description of reimbursement program:

Automobili Lamborghini does not plan to provide notice about reimbursement to owners as all the affected vehicles are still covered under the new vehicle warranty.

Period of reimbursement:**Costs to be reimbursed:****Address for reimbursement claims:**

Recall Schedule

Description of recall schedule:

Customers will be notified by registered mail and customer app while dealers through Lamborghini dealer portal.

Planned Dealer Notification Date: Mar 12, 2026 - Mar 12, 2026 No Dealers**Planned Interim Owner Notification Date:** No Owners**Planned Remedy Owner Notification Date:** Mar 26, 2026 - Mar 26, 2026 Phased Recall**Date when VIN will be searchable:**