



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V141

Manufacturer Name: Chrysler (FCA US, LLC)

Submission Date: Mar 12, 2026

NHTSA Recall No.: 26V141

Manufacturer Recall No.: 26D

Manufacturer Information

Population

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive
CIMS 482-00-91
Auburn Hills MI, 48326-
2757

Total number of potentially involved: 11,767

Estimated percentage with defect: 6.7%

Vehicle Information

Vehicle 1: 2024-2026 JEEP WAGONEER S

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Mar 21, 2024 - Jul 24, 2025

Number of potentially involved: 11,767

Descriptive Information:

Some 2024-2026 MY Jeep Wagoneer S vehicles may have been built with a rear hinge cover with insufficient design tolerances.

The suspect vehicle population began on March 21, 2024, when the 2024 MY vehicle production began, and ended on July 24, 2025, when vehicles were no longer being produced with rear hinge covers that may detach. The suspect population was determined by supplier and vehicle production records.

Similar vehicles not included in this recall were built after the suspect period.

Defect / Noncompliance Description

Description of the defect or noncompliance:

A rear hinge cover with insufficient design tolerances may not be properly clipped into position and may detach from the vehicle.

FMVSS1:

FMVSS2:

Part 573 Safety Recall Report

26V141

Description of the safety risk, including crash, fire, death, injury:

A rear hinge cover which detaches from a vehicle may create a road hazard to operators and occupants of other vehicles, and can cause such vehicles to crash without prior warning.

Description of the cause:

Identification of any warning that can occur:

None. However, the driver may hear a rattling noise while driving or notice that either one or both of the hinge covers are not fully seated.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name: Magna International Inc

Address: 337 Magna Drive
Aurora Foreign States, L4G7K1

Country: Canada

Involved Components

Component Name 1: Cover

Component Description: Rail Rr Rt, Rail Rr Lt, Rail Rr Rt, Rail Rr Lt

Component Part Number: 7LX82DX8AB, 7LX83DX8AB, 7LX82DX8AC, 7LX83DX8AC

Chronology

- On January 8, 2026, the FCA US LLC ("FCA US") Technical Safety and Regulatory Compliance ("TSRC") organization opened an investigation into some 2024-2026 MY Jeep Wagoneer S vehicles that may have been built with a rear hinge cover that can detach from the vehicle and create a road hazard.
- From January 8, 2026, through February 18, 2026, FCA US TSRC met with FCA US Engineering and Manufacturing to review vehicle production records and design changes to the hinge cover to understand potential root cause, customer consequence and vehicle scope.
- As of February 18, 2026, FCA US is aware of 2 customer assistance records, 17 warranty claims and 32 field reports potentially relating to this issue for all markets with dates of receipt ranging from February 11, 2025 to November 6, 2025.

Part 573 Safety Recall Report

26V141

- As of February 18, 2026, FCA US is not aware of any accidents or injuries potentially related to this issue for all markets.
- On March 5, 2026, FCA US determined, through the Vehicle Regulations Committee, that a safety defect exists in certain vehicles.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Replace, Repair

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

FCA US will conduct a voluntary safety recall on all affected vehicles to inspect and, if necessary, repair or replace the hinge cover.

How remedy component differs from recalled component:

The remedy part is a hinge cover with improved design tolerances which allow for proper retention to the vehicle.

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

**03/12/2026: FCA US will notify dealers on or about 03/19/2026 and begin notifying owners on or about 05/01/2026.

Planned Dealer Notification Date: Mar 19, 2026 - Mar 19, 2026 No Dealers

Planned Interim Owner Notification Date: No Owners

Part 573 Safety Recall Report

26V141

Planned Remedy Owner Notification Date: May 01, 2026 - May 01, 2026 Phased Recall

Date when VIN will be searchable: Mar 19, 2026