



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 26V211

**Manufacturer Name:** Keystone RV Company

**Submission Date:** Apr 02, 2026

**NHTSA Recall No.:** 26V211

**Manufacturer Recall No.:** 26-482

### Manufacturer Information

### Population

**Manufacturer Name:** Keystone RV Company

**Address:** PO Box 2000  
2642 Hackberry Drive  
Goshen IN, 46527

**Total number of potentially involved:** 172

**Estimated percentage with defect:** 90%

### Vehicle Information

**Vehicle 1:** 2026-2026 KEYSTONE MONTANA

**Product Category:** Trailers

**Product Type:**

**Fuel / Propulsion:**

**Production Dates:** Aug 25, 2025 - Mar 04, 2026

**Number of potentially involved:** 172

**Descriptive Information:**

Model(s): Montana 3100RL

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

It has been decided that the vehicles in the recall population may have inadequate securement of the underbelly to the drop-down section of the frame.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

Under certain conditions during travel, the underbelly may come loose or detach from the vehicle, leading to an increased risk of a vehicle crash.

**Description of the cause:**

# Part 573 Safety Recall Report

# 26V211

The underbelly may not be secured sufficiently enough to prevent separation from the frame.

**Identification of any warning that can occur:**

The underbelly may appear loose or show signs of separation from the frame.

## Component Manufacturer

**Tier of Supplier:**

**Supplier Type:**

**Name:**

**Address:**

**Country:**

## Involved Components

**Component Name 1:** Underbelly - Woven - 70 1/2" x 360' - Black - w/Fo

**Component Description:** Underbelly - Woven - 70 1/2"

**Component Part Number:** 664694

## Chronology

3/26/2026 – Report was made

3/26/2026 – Investigation opened to determine scope and range.

3/31/2026 – All affected units were put on hold for inspection and repair.

3/31/2026 – Warranty claims for underbelly – loose / torn include 0 claims, claim created start date 8/25/2025 to claim created end date 3/31/2026

3/31/2026 – Keystone Safety Committee reviewed the information and concluded that the data reviewed indicated a unanimous vote for a voluntary recall. Investigation called for to determine affected unit range.

4/1/2026 – Investigation concluded and scope completed.

**Related NHTSA Recall Number:**

## Description of Remedy

# Part 573 Safety Recall Report

# 26V211

**Remedy Type:** Repair

**Consumer Advisories:**  Do Not Drive  Park Outside

**Description of remedy program:**

The remedy is to install two C-channels to the I-beams across the drop-down section of the frame with additional securement points of the underbelly.

**How remedy component differs from recalled component:**

The installation of the two C-channels to the frame and additional securement points of the Underbelly - Woven - 70 1/2" – 664694

**Identify how/when recall condition was corrected in production:**

Units were quarantined, inspected then repaired as indicated by inspection.

## Reimbursement Plan

Manufacturer used general reimbursement plan on file.

## Recall Schedule

**Description of recall schedule:**

Keystone will notify the dealers and owners of the recreational vehicles by letter. A final copy of the owner letter will be provided to NHTSA, along with the dealer repair procedures.

**Planned Dealer Notification Date:** May 28, 2026 - May 28, 2026  No Dealers

**Planned Interim Owner Notification Date:**  No Owners

**Planned Remedy Owner Notification Date:** May 28, 2026 - May 28, 2026  Phased Recall

**Date when VIN will be searchable:** May 28, 2026