



U.S. Department  
of Transportation

National Highway  
Traffic Safety  
Administration

## Part 573 Safety Recall Report

## 26V230

**Manufacturer Name:** Nissan North America, Inc.

**Submission Date:** Apr 09, 2026

**NHTSA Recall No.:** 26V230

**Manufacturer Recall No.:** R26A1

### Manufacturer Information

### Population

**Manufacturer Name:** Nissan North America, Inc.

**Address:** P. O. BOX 685001  
Franklin TN, 37068-5009

**Total number of potentially involved:** 47,928

**Estimated percentage with defect:** 0.1%

### Vehicle Information

**Vehicle 1:** 2009-2010 NISSAN CUBE

**Product Category:** Light Vehicles

**Product Type:** Passenger Car

**Fuel / Propulsion:** Compression Ignition Fuel

**Production Dates:** Oct 10, 2008 - Sep 25, 2010

**Number of potentially involved:** 47,928

**Descriptive Information:**

This defect is specific to Model Year 2009-2010 Nissan Cube vehicles equipped with Takata PSDI-X driver's airbag inflators that were produced within a specific LOT number. No other Nissan or INFINITI vehicles are equipped with this inflator.

### Defect / Noncompliance Description

**Description of the defect or noncompliance:**

The driver's airbag inflator on certain Nissan Cube vehicles may contain an improper body weld seal to the inflator base. As a result of this improper weld, the airbag module may detach from the steering wheel during airbag deployment.

**FMVSS1:**

**FMVSS2:**

**Description of the safety risk, including crash, fire, death, injury:**

If this condition occurs, it may increase the risk of injury to the occupant in the event of a crash where driver's airbag deployment is warranted.

# Part 573 Safety Recall Report

**26V230****Description of the cause:****Identification of any warning that can occur:**

There is no preceding warning.

## Component Manufacturer

**Tier of Supplier:** Tier 1**Supplier Type:** OEM**Name:** TK Services Inc.**Address:** 111 Peyerk Court  
Romeo MI, 48065**Country:** United States

## Involved Components

**Component Name 1:** Driver Airbag Inflator**Component Description:** Airbag Inflator Type PSDI-X, Driver's Side**Component Part Number:** 98560-7991C

## Chronology

Chronology to be supplemented.

**Related NHTSA Recall Number:**

## Description of Remedy

**Remedy Type:** Inspect, Replace**Consumer Advisories:**  Do Not Drive  Park Outside**Description of remedy program:**

# Part 573 Safety Recall Report

# 26V230

Dealers will be instructed to check the serial number on the driver's airbag inflator for a specific LOT number. If the inflator is part of the suspect LOT, the dealer will remove the inflator and replace it with a new inflator manufactured by a different supplier. All repairs will be performed free of charge for parts and labor and may take less than one (1) hour to complete.

**How remedy component differs from recalled component:**

**Identify how/when recall condition was corrected in production:**

## Reimbursement Plan

**Description of reimbursement program:**

Nissan will include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy for vehicles which are no longer under warranty.

**Period of reimbursement:**

**Costs to be reimbursed:**

**Address for reimbursement claims:**

## Recall Schedule

**Description of recall schedule:**

Dealers will be notified on April 23, 2026. Owners of all potentially affected Cube vehicles will be notified beginning on May 27, 2026, to bring their vehicle to a Nissan dealer.

**Planned Dealer Notification Date:** Apr 23, 2026

No Dealers

**Planned Interim Owner Notification Date:**

No Owners

**Planned Remedy Owner Notification Date:** May 27, 2026

Phased Recall

**Date when VIN will be searchable:** Apr 23, 2026