



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V304

Manufacturer Name: General Motors, LLC

Submission Date: May 14, 2026

NHTSA Recall No.: 26V304

Manufacturer Recall No.: N262554630

Manufacturer Information

Population

Manufacturer Name: General Motors, LLC

Address: 29427 Louis Chevrolet
Road
MAIL CODE 480-210-2V
WARREN MI, 48093

Total number of potentially involved: 2,464

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 CHEVROLET SUBURBAN 1500

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Aug 27, 2025 - Apr 18, 2026

Number of potentially involved: 35

Descriptive Information:

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 2: 2025-2025 CADILLAC ESCALADE

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Oct 19, 2024 - Aug 26, 2025

Number of potentially involved: 737

Descriptive Information:

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

Part 573 Safety Recall Report**26V304**

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 3: 2026-2026 GMC YUKON

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Dec 18, 2025 - Apr 29, 2026

Number of potentially involved: 49

Descriptive Information:

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 4: 2025-2025 CADILLAC ESCALADE ESV

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Oct 19, 2024 - Aug 21, 2025

Number of potentially involved: 411

Descriptive Information:

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 5: 2025-2025 GMC YUKON XL

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Mar 27, 2025 - Aug 06, 2025

Part 573 Safety Recall Report**26V304****Number of potentially involved:** 7**Descriptive Information:**

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 6: 2026-2026 CADILLAC ESCALADE**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Sep 13, 2025 - Apr 24, 2026**Number of potentially involved:** 647**Descriptive Information:**

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 7: 2025-2025 CHEVROLET TAHOE**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Oct 24, 2024 - Aug 13, 2025**Number of potentially involved:** 83**Descriptive Information:**

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 8: 2025-2025 GMC YUKON

Part 573 Safety Recall Report**26V304****Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Mar 18, 2025 - Aug 26, 2025**Number of potentially involved:** 12**Descriptive Information:**

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 9: 2025-2025 CHEVROLET SUBURBAN 1500**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Nov 02, 2024 - Jul 26, 2025**Number of potentially involved:** 76**Descriptive Information:**

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 10: 2026-2026 CADILLAC ESCALADE ESV**Product Category:** Light Vehicles**Product Type:****Fuel / Propulsion:** Spark Ignition Fuel**Production Dates:** Sep 11, 2025 - Apr 21, 2026**Number of potentially involved:** 335**Descriptive Information:**

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Part 573 Safety Recall Report

26V304

Vehicles with other size wheels are not included.

Vehicle 11: 2026-2026 GMC YUKON XL

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Nov 07, 2025 - Apr 16, 2026

Number of potentially involved: 21

Descriptive Information:

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Vehicle 12: 2026-2026 CHEVROLET TAHOE

Product Category: Light Vehicles

Product Type:

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Aug 27, 2025 - May 01, 2026

Number of potentially involved: 51

Descriptive Information:

GM and supplier manufacturing records and vehicle service records were used to determine the affected population.

This recall only affects vehicles with 24-inch wheels that (a) received the dealer-installed accessory brake package (RPO 5JL) or (b) received a front hub replacement in service.

Vehicles with other size wheels are not included.

Defect / Noncompliance Description

Description of the defect or noncompliance:

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2025 – 2026 model year Cadillac Escalade and Escalade ESV, Chevrolet Suburban and Tahoe, and GMC Yukon and Yukon XL vehicles with 24-inch wheels. Dealers may have used incorrect bolts to install an

Part 573 Safety Recall Report

26V304

accessory brake package or service the front wheel-hub bearings on these vehicles. The bolts may loosen or deform over time.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If a bolt breaks or completely loosens during vehicle operation, additional load could be placed on the three remaining bolts and lead to partial loss of vehicle control, increasing the risk of a crash.

Description of the cause:

GM's service information and certain accessory brake kits specified incorrect bolts for these wheels.

Identification of any warning that can occur:

Drivers may hear noise or feel vibration from the affected wheel hub.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: BOLT

Component Description: Front Hub Bearing Bolt

Component Part Number: 11605137, 11547070

Chronology

A GM product investigator discovered in April 2026 that the kit provided to dealers for installation of an accessory brake package (RPO 5JL) did not include separate instructions or special fasteners for vehicles equipped with 24-inch wheels, as required by GM's specifications. As a result, dealers may have incorrectly reused production-installed bolts. GM also found that its electronic parts catalog (EPC) did not identify the correct bolt for service operations involving replacement or reattachment of the front hub bearing on vehicles equipped with 24-inch wheels.

Part 573 Safety Recall Report

26V304

Seven field complaints potentially associated with this condition were reported to GM on: January 9, 2025, August 4, 2025, September 13, 2025, October 29, 2025, November 25, 2025, December 18, 2025, and April 13, 2026. GM is not aware of any crashes or injuries associated with this condition. GM's Safety Field Action Decision Authority (SFADA) decided to conduct a safety recall on May 7, 2026.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Dealers will replace the front left and right wheel hub bolts.

How remedy component differs from recalled component:

Properly installed correct bolts will maintain proper attachment.

Identify how/when recall condition was corrected in production:

GM's electronic parts catalogue (EPC) was corrected on May 1, 2026. Containment of the accessory brake package (RPO 5JL) for 24-inch wheels was initiated on May 8, 2026.

Reimbursement Plan

Description of reimbursement program:

Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under warranty, so reimbursement is not offered.

Period of reimbursement:

Costs to be reimbursed:

Address for reimbursement claims:

Recall Schedule

Description of recall schedule:

Dealers will be notified on May 14, 2026. Owner notification of an available remedy is estimated to start

Part 573 Safety Recall Report**26V304**

mailing on June 29, 2026.

Planned Dealer Notification Date: May 14, 2026 - May 14, 2026

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date: Jun 29, 2026 - Jun 29, 2026

Phased Recall

Date when VIN will be searchable: May 14, 2026