



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V342

Manufacturer Name: Tiffin Motorhomes, Inc.

Submission Date: May 27, 2026

NHTSA Recall No.: 26V342

Manufacturer Recall No.: WAY-107

Manufacturer Information

Population

Manufacturer Name: Tiffin Motorhomes, Inc.

Address: 105 2nd Street NW
PO Box 596
Red Bay AL, 35582

Total number of potentially involved: 160

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2027-2027 TIFFIN OPEN TRAIL

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Mar 12, 2026 - May 12, 2026

Number of potentially involved: 1

Descriptive Information:

The recall population includes all motorhomes built at Tiffin Motorhome's Winfield Alabama production plant and that were weighed between December 10, 2025 and May 12, 2025. These motorhomes have an OCCC label that was printed on white labels instead of yellow labels. The motorhomes not involved in the recall have the OCCC label printed on the correct yellow label.

Vehicle 2: 2027-2027 TIFFIN WAYFARER

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Mar 10, 2026 - May 12, 2026

Number of potentially involved: 3

Descriptive Information:

The recall population includes all motorhomes built at Tiffin Motorhome's Winfield Alabama production plant and that were weighed between December 10, 2025 and May 12, 2025. These motorhomes have

Part 573 Safety Recall Report**26V342**

an OCCC label that was printed on white labels instead of yellow labels. The motorhomes not involved in the recall have the OCCC label printed on the correct yellow label.

Vehicle 3: 2026-2026 TIFFIN WAYFARER

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Nov 14, 2025 - May 12, 2026

Number of potentially involved: 43

Descriptive Information:

The recall population includes all motorhomes built at Tiffin Motorhome's Winfield Alabama production plant and that were weighed between December 10, 2025 and May 12, 2025. These motorhomes have an OCCC label that was printed on white labels instead of yellow labels. The motorhomes not involved in the recall have the OCCC label printed on the correct yellow label.

Vehicle 4: 2026-2026 TIFFIN MIDAS

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Nov 17, 2025 - Apr 22, 2026

Number of potentially involved: 33

Descriptive Information:

The recall population includes all motorhomes built at Tiffin Motorhome's Winfield Alabama production plant and that were weighed between December 10, 2025 and May 12, 2025. These motorhomes have an OCCC label that was printed on white labels instead of yellow labels. The motorhomes not involved in the recall have the OCCC label printed on the correct yellow label.

Vehicle 5: 2026-2026 TIFFIN OPEN TRAIL

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion:

Production Dates: Oct 03, 2025 - May 12, 2026

Number of potentially involved: 80

Descriptive Information:

The recall population includes all motorhomes built at Tiffin Motorhome's Winfield Alabama production plant and that were weighed between December 10, 2025 and May 12, 2025. These motorhomes have

Part 573 Safety Recall Report

26V342

an OCCC label that was printed on white labels instead of yellow labels. The motorhomes not involved in the recall have the OCCC label printed on the correct yellow label.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The involved motorhomes have an OCCC label incorrectly printed on an white colored label.

FMVSS1: 120 - Wheels and rims- other than passenger cars

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

Incorrect label colors may lead to difficulties locating the correct information for loading and tire pressure which could increase the risk of an accident.

Description of the cause:

The print settings were inadvertently changed to print on the incorrect white label instead of the correct yellow label.

Identification of any warning that can occur:

There is no warning.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: OCCC Label printed by Tiffin Motorhomes

Component Description: Yellow OCCC Label stating the cargo carrying capacity information.

Component Part Number: VIN specific label, no part number

Part 573 Safety Recall Report

26V342

Chronology

05/11/2026 Tiffin Motorhomes is in the process of combining all production to take place at our Red Bay campus. Motorhomes from our Winfield production facility begin arriving at Red Bay for PDI. 05/12/2026 PDI manager for class C motorhomes begins inspections and discovered that the OCCC label was incorrectly printed on the white label instead of the yellow label. An investigation began. IT was notified and confirmed that the printer settings for the scale at Winfield were incorrect and the OCCC label was programmed to print on the white label. At that time, a shipping hold was put on all Class C units arriving from Winfield until the label could be corrected. IT corrected the printer settings. 05/13/2026 Compliance contacted field service reps and provided a list of stock units that needed to be checked for labels to help determine scope, as well as checking the units arriving for service at the Bob Tiffin Service Center. IT confirmed there was no way to tell when the printer settings were changed. 05/15/2026 Comparing information to the scale weights report showed units weighed in November 2025 were correct, units weighed December 12, 2025 were incorrect. 05/20/2026 May Safety Committee meeting was held, committee unanimously voted to recall due to the FMVSS 120 Non-Compliance. 05/22/2026 Compliance received more information from Tiffin field service techs that OCCC labels printed 12/09/2025 were printed on yellow labels, so population was narrowed to units weighed between 12/10/2025 and May 8, 2026 that had already been invoiced and shipped from our Winfield campus.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Mail Information/Labels

Consumer Advisories: Do Not Drive Park Outside

Description of remedy program:

Tiffin Motorhomes will mail OCCC labels printed on yellow to all owners and dealers in possession of involved motorhomes.

How remedy component differs from recalled component:

The remedy labels will be printed on yellow labels instead of white labels.

Identify how/when recall condition was corrected in production:

05/12/2026 IT corrected the printer settings and all class C motorhomes originally weighed at the Winfield scales were put on a sales hold until the correct label is installed.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Part 573 Safety Recall Report**26V342****Recall Schedule****Description of recall schedule:**

Notification letters including the correctly printed labels will be mailed no later than Friday, July 24, 2026. This will be completed at no cost to the owner.

Planned Dealer Notification Date: Jul 24, 2026

No Dealers

Planned Interim Owner Notification Date:

No Owners

Planned Remedy Owner Notification Date: Jul 24, 2026

Phased Recall

Date when VIN will be searchable: Jul 24, 2026