



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V416

Manufacturer Name: Jayco, Inc.

Submission Date: Jun 30, 2026

NHTSA Recall No.: 26V416

Manufacturer Recall No.: 9903659

Manufacturer Information

Population

Manufacturer Name: Jayco, Inc.

Address: 903 South Main Street
PO Box 460
Middlebury IN, 46540

Total number of potentially involved: 14

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2027-2027 ENTEGRA ACCOLADE

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: May 06, 2026 - Jun 05, 2026

Number of potentially involved: 11

Descriptive Information:

Jayco Inc. determined the population from production records.

Vehicle 2: 2027-2027 JAYCO SENECA

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Recreational Vehicle

Fuel / Propulsion: Compression Ignition Fuel

Production Dates: Apr 15, 2026 - May 21, 2026

Number of potentially involved: 3

Descriptive Information:

Jayco Inc. determined the population from production records.

Defect / Noncompliance Description

Part 573 Safety Recall Report

26V416

Description of the defect or noncompliance:

The front dinette brackets were not being installed. This is a noncompliance with FMVSS CFR 571.207 Seating systems.

FMVSS1: 207 - Seating systems

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The risk is that the dinette assembly may not be adequately secured. During vehicle operation or a sudden stop, the dinette could shift, detach, or collapse, increasing the risk of occupant injury.

Description of the cause:

The front dinette brackets were not installed causing the front dinette not to be secure.

Identification of any warning that can occur:

The front dinette is loose and can be moved easily.

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: Distributor

Name: GLOBAL LINK DISTRIBUTION,CORP.

Address: 700 PATRICIA COURT
ELKHART IN, 46516

Country: United States

Tier of Supplier: Tier 1

Supplier Type: Distributor

Name: S & H METAL PRODUCTS

Address: P.O. BOX 35
TOPEKA IN, 46571

Country: United States

Involved Components

Component Name 1: SCREW,RW QUAD 8.00X1.00 TWFST ZC

Part 573 Safety Recall Report

26V416

Component Description: SCREW,RW QUAD 8.00X1.00 TWFS ZC

Component Part Number: 0214602

Component Name 2: BRACKET,DIN BK SPRT 2.50X29.00 .095 AL ANG

Component Description: BRACKET,DIN BK SPRT 2.50X29.00 .095 AL ANG

Component Part Number: 0264588

Chronology

6/5/26: Jayco engineering informed Compliance via email of a situation where the front dinette securement was not installed. Engineering provided a preliminary scope of 26 and a preliminary instruction.

6/8/26: The incident was reviewed by the Warranty Incident Review Committee (WIRC). The members of WIRC decided to elevate it to the Corrective and Preventive Action Committee (CPAC) due to failing to meet FMVSS code 207 - Seating Systems

6/17/26: The Corrective and Preventive Action Committee (CPAC) met to discuss this incident and elevated it to the Safety Steering Committee (SSC).

6/25/26: The Safety Steering Committee (SSC) met and voted in favor of proceeding with a noncompliance recall for failure to comply with the requirements of 49 CFR § 571.207 - Seating Systems. There have been one complaint and no warranty claims associated with this recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Install bracket to front of dinette and slide out floor.

How remedy component differs from recalled component:

The remedy will be to install the bracket that was previously not installed.

Identify how/when recall condition was corrected in production:

Engineering discovered that the Seneca/Accolade (3HK/3HL/3HM/4HK/4HL/4HM) front dinette brackets

Part 573 Safety Recall Report

26V416

were not being installed on June 5, 2026. Engineering & Production repaired units on campus and informed Jayco Compliance of the final scope on June 17, 2026.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Jayco will notify its dealers and affected retail owners.

Planned Dealer Notification Date: Aug 03, 2026 - Aug 03, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: Aug 03, 2026 - Aug 03, 2026

☐ Phased Recall

Date when VIN will be searchable: Aug 03, 2026