



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V541

Manufacturer Name: Altec Industries, Inc.

Submission Date: Aug 21, 2026

NHTSA Recall No.: 26V541

Manufacturer Recall No.: CSN-3356

Manufacturer Information

Population

Manufacturer Name: Altec Industries, Inc.

Address: 210 Inverness Center Drive
Birmingham AL, 35242

Total number of potentially involved: 55

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2019-2026 ALTEC AN SERIES AERIAL DEVCIE

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Truck

Fuel / Propulsion:

Production Dates: Dec 26, 2019 - Jun 11, 2026

Number of potentially involved: 14

Descriptive Information:

The recall population was determined from a review of production records.

Vehicle 2: 2023-2023 ALTEC AA SERIES AERIAL DEVICE

Product Category: Buses, Medium & Heavy Vehicles

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2023 - Dec 31, 2023

Number of potentially involved: 4

Descriptive Information:

The recall population was determined from a review of production records.

Vehicle 3: 2022-2026 ALTEC DIGGER DERRICK

Product Category: Buses, Medium & Heavy Vehicles

Part 573 Safety Recall Report

26V541**Product Type:****Fuel / Propulsion:****Production Dates:** Jan 01, 2022 - Jun 11, 2026**Number of potentially involved:** 36**Descriptive Information:**

The recall population was determined from a review of production records.

Vehicle 4: 2025-2025 ALTEC AM SERIES AERIAL DEVICE**Product Category:** Buses, Medium & Heavy Vehicles**Product Type:****Fuel / Propulsion:****Production Dates:** Jan 01, 2025 - Dec 31, 2025**Number of potentially involved:** 1**Descriptive Information:**

The recall population was determined from a review of production records.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The Bendix automatic braking system was not recalibrated after Altec relocated the front radar box during installation of the front bumper assembly.

FMVSS1:**FMVSS2:****Description of the safety risk, including crash, fire, death, injury:**

If the system is not recalibrated, it may not respond as designed, potentially delaying braking response and increasing the risk of a crash.

Description of the cause:**Identification of any warning that can occur:**

Chassis instrument panel indicator lights might display a warning that requires investigation.

Part 573 Safety Recall Report

26V541

Component Manufacturer

Tier of Supplier:**Supplier Type:****Name:** Altec Ind. Inc.**Address:** 2106 South Riverside Road
St Joseph MO, 64507**Country:** United States

Involved Components

Component Name 1: Chassis Sales Option - Ben Wingman Fusion**Component Description:** Chassis Sales Option - Bendix Wingman Fusion**Component Part Number:** 970783693

Chronology

On June 25, 2026, during a Bendix programming audit conducted by the chassis team, Altec identified completed vehicles that had not received the required Bendix programming following installation. Altec initiated an investigation to determine whether other complete vehicles were affected. On August 10, 2026, the investigation identified 55 complete vehicles within the affected population. On August 10, 2026, a potential field action investigation was opened to review the scope of the issue. On August 14, 2026, after reviewing the potential field action investigation results, Altec approved the field action. There were no warranty claims or field reports identified. There have been no accidents, injuries or deaths related to this issue.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Inspect, Reimburse, Repair, Software**Consumer Advisories:** ☐ Do Not Drive ☐ Park Outside**Description of remedy program:**

Owners will be asked to present the affected unit for repair so Altec can update the Bendix collision mitigation system with the revised parameters, then calibrate and test the system. The recall remedy will be completed free of charge when presented for repair. The Altec Warranty Policy covers the recall

Part 573 Safety Recall Report

26V541

remedy including cases requiring reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall.

How remedy component differs from recalled component:

The remedy updates the Bendix collision mitigation system with revised parameters, followed by calibration and testing to confirm proper operation in the installed location.

Identify how/when recall condition was corrected in production:

The Bendix collision mitigation system production work instructions include a process to update the system with revised parameters, followed by calibration and testing to confirm proper operation in the installed location.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Altec will issue CSN-3356 to the owners of the affected units. Altec does not have a dealer network and issues letters to owners only.

Planned Dealer Notification Date:

☒ No Dealers

Planned Interim Owner Notification Date: Oct 16, 2026 - Oct 16, 2026

☐ No Owners

Planned Remedy Owner Notification Date:

☐ Phased Recall

Date when VIN will be searchable: