



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V589

Manufacturer Name: Forest River, Inc.

Submission Date: Sep 11, 2026

NHTSA Recall No.: 26V589

Manufacturer Recall No.: 51-2096

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 155

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2024-2026 FOREST RIVER ROCKPORT

Product Category: Buses, Medium & Heavy Vehicles

Product Type: Truck

Fuel / Propulsion:

Production Dates: Feb 21, 2024 - Jul 30, 2026

Number of potentially involved: 155

Descriptive Information:

The scope was determined using a specific lift gate and specific OEM chassis combination, from inception to present date.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The wiring may be positioned too close to the underside of the vehicle hood when the hood is in the closed position. This condition may allow the wire sheathing the rub away and expose the conductors.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The electrical conductor may come into contact with the hood or other grounded vehicle components, resulting in an electrical short, which may lead to a fire and property damage.

Part 573 Safety Recall Report

26V589

Description of the cause:

Production Error

Identification of any warning that can occur:

An operator may notice chaffing wiring under the hood during routine engine inspections.

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: 12V Wiring

Component Description: 12V Wiring

Component Part Number: 12V Wiring

Chronology

August 31, 2026, Forest River's Office of Corporate Compliance was made aware of the concern by the manufacturing plant(s).

September 1, 2026, Forest River's Office of Corporate Compliance began research into the concern.

September 8, 2026, Forest Rivers Corporate Recall Committee voted to Recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Part 573 Safety Recall Report

26V589

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy the wiring path away from the hood.

What is the Forest River Customer Service Phone Number? (574) 522-7599

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Rockport
Forest River, Inc.
Attn: Warranty Manager
914 County Road 1
Elkhart, IN 46516

How remedy component differs from recalled component:

The wiring will be routed or otherwise protected to ensure the sheathing remains intact.

Identify how/when recall condition was corrected in production:

The week of August 31, 2026, the manufacturing plant changed the wiring path of the aftermarket electrical wiring and repaired vehicles in the yards.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Oct 19, 2026 - Oct 19, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: Oct 19, 2026 - Oct 19, 2026

☐ Phased Recall

Part 573 Safety Recall Report

26V589

Date when VIN will be searchable: