



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V603

Manufacturer Name: Forest River, Inc.

Submission Date: Sep 21, 2026

NHTSA Recall No.: 26V603

Manufacturer Recall No.: 40-2097

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 16

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2027 Forest River Grand Sport GT

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Dec 24, 2025 - Jul 31, 2026

Number of potentially involved: 16

Descriptive Information:

The scope was determined using the option code used to manufacture the vehicles.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The "Engine Pre-Heat" option was improperly installed.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The engine coolant hose may fail, causing sudden engine overheating and failure. This condition may lead to a crash.

Description of the cause:

Part 573 Safety Recall Report

26V603

Production Error

Identification of any warning that can occur:

None

Component Manufacturer

Tier of Supplier:

Supplier Type:

Name:

Address:

Country:

Involved Components

Component Name 1: Coolant Hose & 12V Wiring

Component Description: Coolant Hose & 12V Wiring

Component Part Number: Coolant Hose & 12V Wiring

Chronology

On September 10, 2026, Forest Rivers Office of Corporate Compliance was notified by the manufacturing division of the matter. A research item was opened and began.

On September 16, 2026, Forest River identified concerns of inconsistency with the installation of the Engine Preheat Pump.

On September 21, 2026, Forest Rivers Corporate Committee voted to Recall.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Replace, Repair

Part 573 Safety Recall Report

26V603

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to replace or re-pin the oasis harness, replace the coolant hose(s) as needed, and re-rout the hose from pump to the correct side of the harness.

What is the Forest River Customer Service Phone Number? (574) 522-1583

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Forest River Diesel
Forest River, Inc.
Attn: WARRANTY MANAGER
1800 West Hively
Elkhart, IN 46517

How remedy component differs from recalled component:

The 12V wire harness will be re-pinned, the engine coolant hose(s) replaced and rerouted as necessary, the petcock valve(s) opened.

Identify how/when recall condition was corrected in production:

The week of September 16, 2026, Forest River inspected and repaired any vehicle with the concern in the holding yard and in production.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Oct 31, 2026 - Oct 31, 2026

☐ No Dealers

Planned Interim Owner Notification Date:

☐ No Owners

Planned Remedy Owner Notification Date: Oct 31, 2026 - Oct 31, 2026

☐ Phased Recall

Part 573 Safety Recall Report

26V603

Date when VIN will be searchable: