



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Part 573 Safety Recall Report

26V608

Manufacturer Name: Forest River, Inc.

Submission Date: Sep 23, 2026

NHTSA Recall No.: 26V608

Manufacturer Recall No.: 20-2098

Manufacturer Information

Population

Manufacturer Name: Forest River, Inc.

Address: 55470 CR 1
P.O. Box 3030
Elkhart IN, 46515-3030

Total number of potentially involved: 132

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2026 FOREST RIVER CEDAR CREEK

Product Category: Trailers

Product Type:

Fuel / Propulsion:

Production Dates: Oct 11, 2024 - Aug 26, 2025

Number of potentially involved: 132

Descriptive Information:

The scope was determined from inception of the model to model year 2026 where the model received alterations.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The bunkroom door may not open fully when the sleeper sofa is in the bed position, due to the bunkroom door swinging inward into the bunkroom.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If occupants cannot open the door as a means of secondary egress from the bunkroom, this condition may lead to personal injury.

Part 573 Safety Recall Report

26V608**Description of the cause:**

Manufacturing Error

Identification of any warning that can occur:

The bunkroom door may not open when the sofa is deployed into the sleeper sofa position.

Component Manufacturer**Tier of Supplier:****Supplier Type:****Name:****Address:****Country:****Involved Components****Component Name 1:** Bunkroom Door**Component Description:** Bunkroom Door**Component Part Number:** Bunkroom Door**Chronology**

On September 16, 2026, Forest River's Office of Corporate Compliance ("OCC") received a VOQ: 11762673 from NHTSA.

On September 17, 2026, OCC opened a research item into the matter.

On September 21, 2026, Forest River's Corporate Committee voted to recall.

Related NHTSA Recall Number:**Description of Remedy****Remedy Type:**

Part 573 Safety Recall Report

26V608

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River dealer will need to perform the remedy to change the bunkroom door swing into the living quarters of the vehicle.

What is the Forest River Customer Service Phone Number?

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall.

Please send the service invoice to the following address:

Cedar Creek
Forest River, Inc.
Attn: WARRANTY MANAGER
501 Hawpatch Dr
Topeka IN 46571

How remedy component differs from recalled component:

The bunkroom door will swing into the living quarters of the vehicle, allowing the door to open fully.

Identify how/when recall condition was corrected in production:

During the 2026 model year change the manufacturing plant changed the door swing to match the sales literature and the website floorplan.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date: Nov 02, 2026 - Nov 02, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Nov 02, 2026 - Nov 02, 2026 ☐ Phased Recall

Part 573 Safety Recall Report

26V608

Date when VIN will be searchable: