

[Next Unread Message](#)

View Message

Sent on 03 20 2026 **Expires on** 06 08 2026

From PS&P Service Communications

Subject STOP SALE NOTICE: CB1000SP #3 - DISCONNECTED FUEL FEED HOSE

March 20, 2026

Re: STOP SALE NOTICE: CB1000SP #3- DISCONNECTED FUEL FEED HOSE

Dear Honda Dealer:

Honda is issuing a **STOP SALE NOTICE** on **CERTAIN 2025 CB1000SP** motorcycles. Due to a manufacturing assembly error, the fuel feed hose connected to the fuel tank may unexpectedly come off during operation, resulting in engine stalling and fuel leakage, potentially increasing the risk of a crash or injury.

AFFECTED UNITS

As of March 20, 2026, you **MUST NOT SELL ANY NEW** or **USED 2025 CB1000SP** motorcycles until it is repaired according to a forthcoming Service Bulletin.

Certain 2025 CB1000S and CB1000SP motorcycles:

- To search for applicable recalls on a specific unit, you **MUST** use *Unit Information* on **iN**, available March 24, 2026.
- To manage your affected inventory, use your dealer *eResponsibility Report* on **iN**, available March 24, 2026.

SERVICE BULLETIN

Service bulletin *CB1000SP #3*, which includes all information relating to this Safety Recall, will be revised to include all parts and repair information. Dealers will be notified by **iN** message.

CUSTOMER NOTIFICATION

American Honda intends to mail customer letters to all owners of affected motorcycles in late May 2026. Customers will be informed that their motorcycle is affected by this safety-related defect and to make an appointment with an authorized Honda dealer to have their unit repaired.

Make Sure All Departments In Your Dealership Are Aware Of This Safety Recall.

Sincerely,

American Honda Motor Co., Inc.
Powersports Division

MTB 55447 (2603)