

MACK TRUCKS RECALL ALERT



Subject: SC0494 EPM X3 connector Exposed
Recall Number: SC0494
Date: April 28, 2026
Applicable Markets: U.S. Canada Mexico Export

Description

Certain Mack Pioneer PR (4) and Anthem AN (4) vehicles may be equipped with rear brake modulator(s) with unprotected electrical connector(s) that could short-circuit, leading to a loss of Anti-lock Brake and Electronic Stability Control systems. Loss of ABS and ESP systems increases the risk of a crash or injury.

Model and Model Years Affected

Certain MY 2025 - 2027 Pioneer PR (4) and Anthem AN (4) model vehicles manufactured from October 22, 2024 through April 8, 2026.

Vehicle Quantities

2,776 vehicles (2,337 US, 210 Canada, 118 Mexico and 111 Export)

Dealer Responsibilities

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act require dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Notification Release Schedule

- Vehicle list will be posted on the Trucks Dealer Portal 4/30/2026.
- Owner notification letters will be released on or before 6/22/2026.
- Repair Instruction will be released once they are available.

Contact

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.