



RETAILER BULLETIN

15 – June - 2026			BULLETIN NO: 262706.036			DEPT: CUSTOMER SERVICE						
AUDIENCE:	DEALER PRINCIPAL	X	SALES MGR		SALES GUIDES		SERVICE MGR	x	TECHS		PARTS STAFF	X
	GENERAL MANAGER		BUSINESS MGR		OFFICE MGR		SERVICE ADVISORS	x	PARTS MGR	X	WARRANTY	X
SUBJECT: D127 – Fuel Tank Wall Thickness Concern												

JLR North America, LLC has identified a concern on certain 2026 model year Defender and Discovery vehicles, where the fuel tank wall thickness may be below design specification in the area of the fuel tank inlet check valve.

See Service Action D127 for campaign details and use of the parts below.

Powertrain	Part #	Description
V8 T/C 4.4L Petrol	202123518 1/ vehicle	Fuel Tank
V8 T/C 4.4L Petrol	126123538 2/ vehicle	Exhaust Clamp
Ingenium I6 3.0L Petrol Ingenium I4 2.0L Petrol	202123489 1/ vehicle	Fuel Tank
Ingenium I6 3.0L Petrol Ingenium I4 2.0L Petrol	RYG500270 2 vehicle	Rear Driveshaft Center Bearing Bolt
Ingenium I6 3.0L Petrol	LR125187 1/ vehicle	Exhaust Clamp
Ingenium I4 2.0L Petrol	126123561 1/ vehicle	Exhaust Clamp
All	LR117476 1/ vehicle	Gasket
All	LR092696 6/ vehicle	Rear Driveshaft Bolt
All	TYF500020 3/ vehicle	Rear Driveshaft Washer
All	LR034506 1/ vehicle	Kit O-Ring

See Service Instructions for further details

Parts Managers / Professionals:

- Due to the very small numbers of vehicles affected by this safety recall, a proactive parts allocation (Parts Push) will not be used to distribute initial parts for this campaign.
- To speed up the release of parts orders, add D127 and the complete VIN on Customer Material Line on the order for each part.
- Vehicles affected by this Safety Recall are shown below.

QUESTIONS ABOUT THIS BULLETIN? PLEASE CONTACT:

David Woods
Parts MTO & Technical Supervisor
Dwoods4@jaguarlandrover.com

Campaign Ref No	VIN Number	Model Year	Vehicle Sale Date	Ordering Dealer Country	Ordering Dealer CI Code	Ordering Dealer Name
D127		2026		USA	R0143	Land Rover Charlotte
D127		2026		Canada	R0559	Land Rover Waterloo
D127		2026		USA	P4038	Land Rover Denver
D127		2026		USA	P4038	Jaguar Land Rover North America, LLC - Port Hueneme
D127		2026		USA	R0680	Land Rover Tampa
D127		2026	07/04/2026	USA	R0391	Land Rover Palm Beach
D127		2026	04/04/2026	USA	R0395	Land Rover Jacksonville
D127		2026	30/03/2026	Canada	R2082	Land Rover Enterprise - Ontario

For more information, please contact David Woods, dwoods4@jaguarlandrover.com, or the JLR Parts Technical Team at jlrpartstech@jaguarlandrover.com