


Important: Safety Recall 26V280



Dear Dealer Partner,

This notice is to inform you of BraunAbility Safety Recall, associated with NHTSA Recall No. **26V280**, applicable to **2025 and 2026 Dodge Promaster** units equipped with the affected installation. We show the above listed four units are currently in your Chino store inventory.

Please see enclosed Service Bulletin 610572 , which outlines the required procedure, including removal and repositioning of the seat base and installation of new seat bases and U-bolts using Installation Kit **610822KS**. The standard labor time for this repair is **1.0 hour**.

Action Required

- Perform the recall procedure on all affected vehicles in your inventory (parts have been included in this shipment)
- This work **must be completed prior to retail sale or delivery of the unit** to the end customer. Vehicles should not be retailed until the recall repair has been successfully completed.



Warranty Claim Instructions

To receive reimbursement for this recall repair:

1. Submit a warranty claim in accordance with normal BraunAbility procedures.
2. When entering the claim, select the following topics:

Warranty Topics: Recall / 26V280 / Repair

3. Reference Safety Recall **610572 Rev. 1** in your claim documentation.
4. Use the published labor time of **1.0 hour**.

If you have any questions about identifying affected vehicles, completing the repair outlined in Service Bulletin 610572, or submitting the warranty claim, please create a Help ticket on BraunAbility Connect+ for assistance.

Thank you for your prompt attention to this safety-related recall and for your continued partnership.

Sincerely,

BraunAbility Customer Care & Aftersales Team

Enclosure: Quantity 4 – Installation Kit #610822KS

Quantity 4 – Service Bulletin #610572