



MICRO BIRD

DATE: June 2026
TO: Micro Bird Distributors
SUBJECT: Recall 26-121-OUC / NHTSA Recall 26V286

This notice is sent to you in accordance with the requirements of the Motor Vehicle Safety Act. This is to inform you that your school vehicle(s) may contain a defect that could affect the safety of a person.

Micro Bird has decided that a defect which relates to motor vehicle safety exists in certain 2023-2026 G5 vehicles equipped with a second air conditioning compressor kit.

So that we can notify you of recalls affecting your vehicle(s), it is important that you inform us of any change or error in your mailing address, vehicle ownership or status. Please send the completed form at the bottom of this letter to recall@microbird.com using Address/Ownership Change in the Subject area.

In the recalled vehicles equipped with a second air conditioning compressor kit, the engine driving belt pulley may rub against the oil lines. Should the pulley rub against an oil line sufficiently to damage it and cause leaks, the risk of a fire increases. If so, the risks of injury would also be increased.

To complete this recall, owners will contact you to make an appointment to have their vehicle(s) corrected. The correction consists in adding a fastening device to secure the engine oil lines away from the driving belt pulley.

Micro Bird Corporation will provide correction instructions, as well as provide required equipment and reimburse labor to mitigate this recall at no charge.

Important: We want to remind you that recalled vehicles must be corrected before you sell, lease, or deliver them; vehicles returned at the end of a lease must be corrected before they can be offered for sale as used vehicles.

We apologize for any inconvenience this situation may cause and we thank you for your cooperation.