

D120 – Driver’s Airbag Potential Non-Deployment
D120 Safety Recall Overview

- **Affected Vehicles**
 - Defender (2020-2026 MY)
 - Discovery (2021-2026 MY)
 - Range Rover (2022-2026 MY)
- **Issue**
 - Possible non-deployment of the driver's airbag
 - Increased risk of injury or death in a crash
 - In certain vehicles, the driver's airbag may not deploy
 - Increased risk of injury or death in a crash
- **Retailer / Warranty Administrator Actions**
 - Confirm campaign status
 - Unsold affected vehicles
 - Check for additional repairs
 - Customer notification
 - Dealer/Government agencies

Please refer to the latest version of the bulletin released on July 14th for the latest instruction information.

Subject: Driver's Airbag Potential Non-Deployment

Publication No: D120v4

D120 – Driver’s Airbag Potential Non-Deployment
Warranty Claiming & Repair Strategy

- **Repair Description**
 - Remove driver’s airbag
 - Apply approved
 - Reinstall
 - **Claim Considerations**
 - Option
 - Ex
 - Syrn
 - Gel lo
 - Drive In
 - Drive In
 - **Sundry Allowances**
 - TECGEL 7436 EC
 - Syringe + 18Ga blun
 - One syringe can be used for 15 repairs and claimed once per 15 vehicles
- connector terminals.
- solely for this recall.

Please refer to the latest version of the bulletin released on July 14th for the latest instruction information.

Subject: Driver's Airbag Potential Non-Deployment

Publication No: D120v4