

DATE: 07/16/2026

TO: My Communication

SUBJECT: SAFETY RECALL NOTICE – STOP DELIVERY: F1035

On **June 26, 2026**, Daimler Truck North America (DTNA) filed a Defect Information Report (DIR) with the National Highway Traffic Safety Administration (NHTSA) and/or a Defect Information Notice (DIN) with Transport Canada (TC) informing the agencies of our intent to conduct a voluntary safety recall.

It is a violation of Federal Law for a dealer or distributor to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. **Some of the vehicles subject to this "Stop Delivery Notice" may be in your new vehicle inventory.** Until further instructions are available, **new vehicles subject to this "Stop Delivery Notice" must be held and not be delivered to customers.**

DTNA also strongly recommends that dealers and distributors remedy Recalls before selling *used* vehicles. For any used vehicle with an open recall not remedied before sale, DTNA requires that the dealer or distributor notify prospective buyers of the open recall.

Please ensure that the registration information for vehicles subject to this recall is up to date to facilitate accurate owner notification.

Affected Vehicles in F1035:

Make	Model	Model Year Start	Model Year End	Production Start Date	Production End Date
Thomas Built Buses	SAF-T-Liner EFX2	2026	2027	11/19/2025	03/09/2026
	SAF-T-Liner HDX2	2026	2027	03/05/2025	04/08/2026

Problem: A defect, which relates to motor vehicle safety, exists in certain model year 2026 and 2027 Thomas Built Buses (TBB) Saf-T-Liner HDX 2 and Saf-T-Liner EFX 2 buses equipped with a battery-operated entrance door solenoid system. The vehicles have a driver-operated entrance door switch and a timer relay used to prevent battery drain from the solenoid. An incompatibility between certain door electronic components could prevent the door from responding to the operator's input via the door switch.

Owner Notification Mailing Schedule: 08/25/2026

Colleagues,

Please see the attached Stop Delivery Notice regarding a pending safety recall:

- **Recall #:** F1035
- **Subject:** TBB Entrance Door Switch
- **Population:** 156

We are providing this instructional communication to address new vehicles that are currently in dealer or distributor inventory (e.g. new trucks that have not yet been put into service).

These new vehicles are to be held until the subject recall has been completed. If a dealer or distributor has a new vehicle included in the safety recall in their inventory to be sold, the defect condition must be corrected before releasing it to a customer. It is a violation of Federal Law for a dealer or distributor to deliver a new motor vehicle with an open recall.

For a complete list of vehicles ordered by your location, impacted by this recall, please run OWL Campaign Report CM012 – Pending and Interim Without Repair Recall Notification VIN List.

If you have any questions regarding this information, please contact the DTNA Campaigns Group at 503-745-7366 or email DTNA-WAR-Campaigns@DaimlerTruck.com. For issues running the CM012 report, please file a WSC (Warranty Support Center) ticket.

Thank you,

DTNA Campaigns Management