



FORETRAVEL
MOTORCOACH

Brake Pressure Switch 26V-486

Foretravel Dealer:

Introduction: Foretravel has determined on the model year 2025, 2026, Foretravel Realm and FS605P vehicles including a limited number of 2027 Foretravel Realm FS605P vehicles. The brake pressure switch used in the air brake system may retain enough residual air pressure causing the brake lamps to be illuminated when the service brakes are not applied.

Units Affected: Production build #'s 9235 thru 9298. There are 12 vehicles that are not involved in this Recall, only vehicles that have customer notification letters are included in this Recall.

Please Note: Foretravel Motorcoach has 51 vehicles involved with this recall.

Action: The recall remedy is to replace defected pressure switches.

Solution: Spartan will supply new pressure switches with a pressure setting that will cause the brake lamps to not be illuminated with residual air pressure. The repair is expected to up to 1 hour and will be performed at no charge.

Foretravel will notify owners of the affected vehicles and direct them to the nearest service center to have the remedy applied.

For additional assistance, you may call Foretravel Inc. at 800-955-6226 and ask for Technical Support or you can contact Spartan RV Chassis Customer Product and Support at 1-800-543-4277

We regret any inconvenience this situation may cause. Foretravel Inc. and The Shyft Group, Inc. and its brands are committed to customer safety and satisfaction.

Labor: 1.00 hr. for replacement of pressure switches

Part #: Spartan # PN 0108-GG3-015 2 EA

Note: Brake lamps that are illuminated without the service brake being applied could be confusing to trailing drivers and could increase the risk of a crash.

Brake lights could be illuminated without warning.