



Service Engineering Operations
Customer Service Division

Ford Motor Company
PO Box 1904
Dearborn, Michigan 48121

September 11, 2026

TO: All U.S. Ford and Lincoln Dealers

**SUBJECT: NEW VEHICLE DEMONSTRATION / DELIVERY HOLD - Advance Notice
Safety Recall 26S64**
Certain 2026 Model Year Bronco Vehicles
Right-Hand Side Curtain Airbag Tear

AFFECTED VEHICLES (U.S. Population Of Affected Vehicles 2,710):

Vehicle	Model Year	Assembly Plant	Build Date Range
Bronco	2026	Michigan	June 27, 2026 through July 26, 2026

Affected vehicles are identified in OASIS and FSA VIN Lists.

REASON FOR THIS SAFETY RECALL

On some affected vehicles, a bracket in the right-hand side curtain airbag assembly may have a sharp raised edge. During airbag deployment, this edge may tear the side curtain airbag. A tear in the right-hand side curtain airbag may cause it to deflate more quickly, potentially increasing the risk of occupant injury in a crash.

SERVICE ACTION

DO NOT DEMONSTRATE OR DELIVER any new in-stock vehicles involved in this safety recall. For new vehicle storage guidelines, refer to EFC13033, Storage Guidelines for New Vehicles.

A complete dealer bulletin, including technical instructions, is expected to be available to dealers by September 30, 2026, when a remedy is planned to be available for this safety recall.

IMPORTANT: Dealers should open a Repair Order (RO) only when a full dealer bulletin is published. Opening an RO against an Awareness or Advance Notice will result in warranty rejections against a recall.

OWNER NOTIFICATION

Owners of record will be notified via first-class mail within sixty days, which may occur before remedy availability including repair instructions have been provided to dealers.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$27,168 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery.

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety recall. Please consult your legal counsel for legal advice.

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician System (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Customer Service Division