



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

IMPORTANT SAFETY RECALL INFORMATION




Issued in Accordance
With Federal Law



SAFETY RECALL



\*\*\*\*\*SNGLP



000001
T1 P1

26PACA

Recall Notice: 26PACA

SAFETY RECALL



March 12, 2026

Subject: 26PACA: Right-Hand (RH) Steering Cross Shaft Misaligned  
NHTSA: 26V022  
Expiration Date: None

## **IMPORTANT SAFETY RECALL**

This notice applies to your vehicle(s) with VIN(s) listed at the bottom or back of this page.

Dear Peterbilt Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors Company has decided that a defect which relates to motor vehicle safety exists in certain model year 2025 Model 520 and 520 BEV chassis manufactured between 10/09/2023 and 08/06/2025 with right-hand stand-up steering configuration.

<b>What is the problem?</b>	The Right-Hand (RH) steering cross shaft bearing mounting holes may be misaligned, resulting in increased stress on the steering cross shaft for the Right-Hand Stand-Up (RHSU) controls. Failure of the RH steering cross shaft may result in the loss of RH steering control which may increase the risk of a crash.
<b>What will your dealer do?</b>	Dealers will inspect for steering cross shaft misalignment. Repairs and/or adjustments will be made as necessary to realign the steering shaft bearings, free of charge.
<b>What should you do?</b>	Contact your dealer immediately to schedule a repair. This repair may require up to 4 hours of labor.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at [www.Peterbilt.com](http://www.Peterbilt.com). When scheduling this repair, please refer to recall 26PACA: Right-Hand (RH) Steering Cross Shaft Misaligned and the VIN(s) listed in this letter. You may be eligible for reimbursement if you performed this repair before receiving notification of the recall. For more information, please e-mail [servicebulletins@PACCAR.com](mailto:servicebulletins@PACCAR.com).

If you believe this remedy was not available to you within a reasonable amount of time and free of charge, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590; call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or visit <http://www.safercar.gov>.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to [servicebulletins@paccar.com](mailto:servicebulletins@paccar.com).

We appreciate your attention to this matter and value your loyalty to Peterbilt and its dealer network.

Sincerely,

Peterbilt Customer Service

Our records indicate that these vehicles are affected by 26PACA and are owned by [REDACTED]

