

20 March 2026

## ! IMPORTANT SAFETY RECALL !

### REMOVAL OF ALTERNATOR TO MAIN HARNESS CONNECTOR

Safety Recall: SRAN641  
NHTSA Recall: 26V078

**This notice applies to your motorcycle:**

**Model:** (2022) Street Scrambler, Street Scrambler Sandstorm, Street Twin, Street Twin Goldline  
(2022 – 2024) Bonneville T100, T120 & T120 Black  
(2023 – 2024) Scrambler 900, Speed Twin 900  
(2024) Bonneville T120 DGR

**VIN:** **SMTXXXX**

Dear **FIRST LAST**:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Triumph Motorcycles Ltd. has decided that a defect which relates to motor vehicle safety exists in your motorcycle, with the VIN shown above. Triumph is conducting a safety recall to address the condition.

**The reason for this recall notice:** The connection system may suffer significant damage and may not function, resulting in decreased alternator performance, thereby increasing the risk of an injury. In extreme cases, there have been reports of smoke and signs of overheating, including scorched connectors and thermal damage to surrounding components. **A similar repair (the introduction of a Wire Alignment Clip) may have been carried out on your motorcycle in the last two years. Your motorcycle, if previously repaired with a Wire Alignment Clip, needs to be repaired under this fresh recall campaign.**

**What Triumph Motorcycles Ltd & your dealer will do:** Triumph Motorcycle Dealers will replace the current 2-piece connector body with a single in-line crimped solution for each of the three alternator assembly wires. This repair should take around 20 minutes. However, depending upon the dealer's work schedule, it may be necessary to make your motorcycle available for a longer period.

**What you must do to ensure your safety:** Please make an appointment with your authorized Triumph motorcycles dealer to have this important remedy performed on your motorcycle as soon as possible.

**Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.**

**If you need help:** Please contact your authorized Triumph dealer should you have any questions or encounter any difficulty regarding this recall. In the event your dealer is unable to remedy your motorcycle, please contact Triumph Motorcycles America at 1-678-854-2010.

If your dealer fails or is unable to remedy this defect without charge, or within a reasonable amount of time, you may submit a written complaint to Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE., Washington, D.C., 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <https://www.nhtsa.gov>.

If you no longer own the motorcycle listed above, please contact Triumph at 1-678-854-2010 and provide any information you can furnish that will assist us in locating the new owner.

We apologise for any inconvenience this may cause you. However, we have taken this course of action in the best interest of your safety and your continued satisfaction with your Triumph motorcycle. We appreciate your attention and cooperation in this important matter.

Sincerely,

Triumph Motorcycles America Ltd.